



Geotechnical and Environmental Sciences Consultants

**RECEIVED**

APR 01 2005

ENVIRONMENTAL PROTECTION

**HAZARDOUS BUILDING MATERIALS SURVEY  
SILVER STRIKE MOTEL  
201 NORTH MAIN STREET  
TONOPAH, NEVADA**

6-000623

**PREPARED FOR:**

Mr. Charlie Rodewald  
Nye County Grants Administration Office  
P.O. Box 153  
Tonopah, Nevada 89049

**PREPARED BY:**

Ninjo & Moore Geotechnical and Environmental Sciences Consultants  
3155 East Patrick Lane  
Las Vegas, Nevada 89120

March 31, 2003  
Project No. 301218001



March 31, 2003

Project No. 301218001

Mr. Charlie Rodewald  
Nye County Grants Administration Office  
P.O. Box 153  
Tonopah, Nevada 89049

Subject: Hazardous Building Materials Survey  
Silver Strike Motel  
201 North Main Street  
Tonopah, Nevada 89049

Dear Mr. Rodewald:

In accordance with your authorization to proceed, Ninyo & Moore has performed a Hazardous Building Materials Survey of the Silver Strike Motel buildings located at 201 North Main Street, in Tonopah, Nevada. The attached report presents our methodology, findings, conclusions, and recommendations regarding our survey.

We appreciate the opportunity to be of service to you on this important project. Should you have any questions regarding this report, please contact the undersigned at your convenience.

Sincerely,  
**NINYO & MOORE**

A handwritten signature in black ink, appearing to read "Robert M. Troisi".

Robert M. Troisi, C.E.M.  
Managing Principal of Environmental Sciences

RMT/ltk

Distribution: (8) Addressee

## TABLE OF CONTENTS

	<u>Page</u>
1. INTRODUCTION .....	1
2. PURPOSE AND SCOPE OF SERVICES.....	1
3. SITE DESCRIPTION.....	1
4. PHYSICAL LIMITATIONS .....	2
5. SAMPLE COLLECTION .....	3
5.1. Asbestos Survey.....	3
5.2. Paint Survey.....	3
5.3. Hazardous Building Material Survey .....	4
6. LABORATORY ANALYSES AND RESULTS .....	4
6.1. Asbestos .....	4
6.2. Paint .....	4
6.3. Miscellaneous Hazardous Building Materials .....	5
7. FINDINGS AND OPINIONS .....	5
7.1. Asbestos .....	5
7.2. Paint .....	5
7.3. Miscellaneous Hazardous Building Materials .....	6
8. RECOMMENDATIONS.....	6
9. LIMITATIONS.....	7

### Tables

- Table 1 – Asbestos Survey Results  
Table 2 – Lead-based Paint Survey Results  
Table 3 – Summary of Hazardous Building Materials

### Figures

- Figure 1 – Site Location Map  
Figure 2 – Site and Vicinity Map  
Figures 3 through 8 – Sample Location Maps

## 1. INTRODUCTION

In accordance with your request and authorization to proceed, Ninyo & Moore has performed a Hazardous Building Materials Survey (HBMS) of the Silver Strike Motel buildings located at 201 North Main Street in Tonopah, Nevada (Figure 1).

This report has been prepared in accordance with generally accepted environmental science and engineering practices. The report is based upon conditions at the subject buildings at the time of the sampling activities, and provides documentation of our findings and recommendations.

## 2. PURPOSE AND SCOPE OF SERVICES

The objective of the surveys was to identify and quantify building materials containing asbestos and/or lead-based paint (LBP), and to quantify potential mercury-containing thermostats/switches, polychlorinated biphenyl (PCB)-containing items (e.g., light ballasts, switches, and transformers), fluorescent light tubes, air conditioning units, and exit signs. Ninyo & Moore performed the services listed below.

- Visual assessment of accessible areas of selected on-site buildings to evaluate the possible presence of asbestos-containing materials (ACMs) and LBPs.
- Collection of 19 paint chip samples of potential LBP content.
- Collection of 70 suspect building material samples and submittal of these samples to an independent laboratory for analysis of asbestos content.
- Visual identification and quantification of air conditioning units, potential mercury-containing thermostats/switches, PCB-containing items, fluorescent light tubes, and exit signs.
- Preparation of this HBMS report, which presents our data and summarizes the assessed materials. This report includes sample location maps, a site description, laboratory testing information, conclusions and recommendations, tables summarizing the building materials assessed, and quantities of identified materials.

## 3. SITE DESCRIPTION

The subject site consists of five buildings and a pool area located at 201 North Main Street in Tonopah, Nevada. The layout of the buildings as they relate to the property boundaries is

presented on Figure 2. Building numbers 1 and 2 are single-story buildings constructed of brick walls and concrete slab floor, with wallboard and plaster interior walls, and stucco exterior siding. Floors are finished with vinyl sheet flooring, vinyl floor tile, and carpet. The walls and ceilings have a variety of finishes consisting of plaster, drywall, and an applied texture coating. The roofs are composed of asphalt shingles, rolled-on roofing, and roofing mastic.

Building 3 is a two-story building constructed on a concrete slab with concrete masonry block walls and wood-framed walls with exterior wood siding. Floors are finished with vinyl sheet flooring, vinyl floor tiles, and carpet. The interior finishes are acoustical ceiling tiles and dry wall.

Building 4 consists of a two-story building with an attached one-story building, which served as the manager's apartment. The buildings are wood-framed walls constructed on a concrete slab with exterior wood siding. The interior finishes consisted of drywall, vinyl floor tile, vinyl sheet flooring, carpet, and acoustical ceiling tiles.

Building 5 is a one-story building with a downstairs garage and basement area. The building is wood frame and concrete masonry block wall construction with exterior wood siding. The interior finishes include drywall, vinyl floor tile, vinyl sheet flooring, and carpet. The roof consists of a roll-on roofing material and mastic.

The pool is located adjacent to Building 1, 2, and 3 and is constructed of concrete materials. A chain link fence and block wall surround the pool area which is partially covered by a small roof that has asphalt shingles.

#### **4. PHYSICAL LIMITATIONS**

At the time of the survey, some limitations were encountered at the site. Ninyo & Moore personnel were not able to access all of the units due to being locked with no keys available or the unit doors were nailed closed. Ninyo & Moore personnel were not able to access the roofs of the two-story structures due to their height.

## 5. SAMPLE COLLECTION

From March 6 through March 8, 2003, Ninyo & Moore personnel conducted a limited asbestos and limited LBP survey at the site. The surveys followed U.S. Environmental Protection Agency (USEPA) guidelines, within the limitations of the scope of this assessment. The survey was performed by a Nevada Certified Asbestos Consultant, and consisted of collecting building materials suspected to contain asbestos from the subject structures, and quantifying miscellaneous hazardous building materials.

### 5.1. Asbestos Survey

A preliminary visual assessment and bulk-sampling survey of suspect ACMs was performed on all of the buildings included in the survey. Representative samples of these suspect ACMs were collected after identification of homogeneous sampling areas (areas in which the materials are uniform in color, texture, construction or application date, and general appearance). Each homogeneous area was observed for material type, location, condition, and friability. Representative samples were collected from each area of proposed demolition, except areas that were inaccessible, or areas of assumed ACM, within the limitations of the survey. Samples were collected using USEPA-recommended sampling procedures. Building materials that were sampled and analyzed for the presence of asbestos are presented in Table 1, and the locations of bulk asbestos samples are shown on Figures 3 through 8.

### 5.2. Paint Survey

Ninyo & Moore assessed the painted surfaces of the subject site to determine possible release to the environment from damaged flaking paint on the buildings and ground, for possible waste characterization, and for contractor worker safety. Representative paint chip samples were collected and sent to a laboratory for chemical analysis for lead content. The survey was conducted in general accordance with accepted environmental science and engineering practices. A total of 19 paint chips were collected and analyzed. The summary of sample results is presented on Table 2 and the locations are presented on Figures 3 through 8.

### **5.3. Hazardous Building Material Survey**

A visual assessment and quantification of potential mercury-containing thermostats/switches, PCB-containing light ballasts, fluorescent light tubes, transformers, air conditioning units, and an exit sign was performed. Hazardous building materials identified at the site are presented in Table 3.

## **6. LABORATORY ANALYSES AND RESULTS**

The following sections describe the laboratory analyses, laboratory results and survey results regarding materials and equipment surveyed, and samples collected during the survey.

### **6.1. Asbestos**

Seventy samples of suspect ACMs were collected and transferred to EMC Laboratories (EMC) for analysis. EMC is a laboratory accredited in the National Voluntary Laboratory Accreditation Program (NVLAP) for bulk asbestos fiber analysis. Because of material layering, of the 70 samples collected, 143 separate analyses were performed. The samples were analyzed for the presence and quantification of asbestos fibers, using polarized light microscopy with dispersion staining (PLM/ds) in general accordance with USEPA Method 600/M4-82-020. The lower limit of reliable detection for asbestos using the PLM method is approximately 1% by volume. Materials in which no asbestos was detected are defined in the laboratory report as no asbestos detected. Materials containing asbestos in amounts less than 1% but greater than 0.1% are defined as containing "trace" amounts. Suspect materials sampled and the analytical results are summarized in Table 1. Copies of the laboratory analytical reports and chain-of-custody records are presented in Appendix H.

### **6.2. Paint**

Nineteen lead-based paint chip samples were collected and sent for analysis by the inspector to EMC Labs, Inc. as per the EPA SW-846 Method 7420 guidelines. A description of the areas

sampled and the results of the analysis are included in Table 2. A copy of the laboratory analytical reports and chain-of-custody record is presented in Appendix H.

### **6.3. Miscellaneous Hazardous Building Materials**

Hazardous building materials visually identified at the site are presented on Table 3 of this report. Positive identification of these materials, via analytical testing, was not performed.

## **7. FINDINGS AND OPINIONS**

The findings of this survey are based on our visual observations; limited analysis of suspect building materials, document review, and paint chips collected from the subject site.

### **7.1. Asbestos**

Based on the analytical results of bulk samples collected during this limited survey, asbestos-containing materials (ACMs) are located in all of the buildings where samples were obtained. We observed certain areas of the buildings were significantly damaged from water intrusion causing roof collapse and other areas were damaged by vandalism. The presence of ACMs in a building does not necessarily mean that the health of the occupants is endangered. If these materials are in good condition and have not been disturbed or deteriorated, exposures are expected to be negligible. However, when ACM deteriorates, is disturbed, or is in damaged condition, such as during renovation operations, asbestos fibers may be released, creating a potential health hazard for building occupants, maintenance personnel, and contractors.

### **7.2. Paint**

Based on the analytical results of paint chips collected during our survey, there were no lead concentrations reported greater than  $1.0 \text{ mg/cm}^2$ , 5,000 mg/kg, or 5,000 ppm at the subject site.

### 7.3. Miscellaneous Hazardous Building Materials

The results of our visual assessment and quantification of potential mercury-containing thermostats/switches, PCB-containing items (e.g., light ballasts, switches, and transformers), fluorescent light tubes, air conditioning units, and exit signs are listed on Table 3. Hazardous or potentially hazardous building materials found at the site included, fluorescent light ballasts, freon-containing air conditioning units, fluorescent light tubes, and a lead-acid battery.

## 8. RECOMMENDATIONS

Since ACMs and miscellaneous hazardous or potentially hazardous building materials have been identified at the subject site, the following recommendations and precautions are provided:

- In accordance with Nevada Administrative Code (NAC) 618.951 "*Exemption of Certain Activities from Requirements*," vinyl asbestos floor tile, exterior roofing materials, exterior siding, drywall joint compound and other non friable materials may stay in place during normal demolition activities. However, if these materials are to be sent through a grinder during demolition, they must be removed completely prior to any grinding activities. To remain eligible for this exemption, the ACM:
  - May not be sanded, power sawed, or drilled.
  - Removed in the largest sections practicable and carefully lowered to the ground.
  - Handled carefully to minimize breakage throughout removal, handling, and transportation to an authorized disposal site.
  - Wetted before removal and during subsequent handling, to the extent practicable.
- The ceiling texture in Building 2 Unit 8, the wall texture of Building 2 Unit 10, the wall texture of Building 3 Unit 19, the wall texture of Building 4 Unit 35, and the exterior bathroom vent pipes of Building 2 were reported to contain asbestos greater than 1%. These ACMs are considered non-exempt and must be removed by a Nevada Asbestos Abatement Contractor prior to demolition.
- Prior to demolition work, a Nevada Asbestos Abatement Consultant should prepare a bid specification document, perform abatement project planning, site and air monitoring, project oversight, and reporting.

- There is a possibility that additional suspect ACM may be found during demolition. Ninyo & Moore recommends that should additional suspect materials, not sampled or assessed in this report, be uncovered during renovation or demolition; (a) samples of suspect materials should be collected for laboratory analysis, and all activities which may impact the materials should cease until laboratory analysis is completed, or; (b) the materials should be assumed to be asbestos-containing and handled as such.
- Prior to building demolition, potential PCB-containing items (e.g., light ballasts), potential freon-containing air conditioning units, and fluorescent light tubes should be removed and properly recycled or disposed by a licensed contractor in compliance with all federal, state and local environmental regulations.

## 9. LIMITATIONS

Ninyo & Moore's opinions and recommendations regarding environmental conditions, as presented in this report, are based on limited sampling and analysis. Further assessment of potential adverse environmental impacts may be accomplished by a more comprehensive assessment. The samples collected and used for testing, and the observations made, are believed to be representative of the area(s) evaluated. However, if additional suspect ACM is encountered during renovation or demolition activities, these materials should be sampled by qualified personnel, and analyzed for asbestos content prior to further disturbance. In addition, please note that quantities of ACMs are approximate. These numbers should be confirmed prior to removal or repair activities.

The environmental services described in this report have been conducted in general accordance with current regulatory guidelines and the standard-of-care exercised by environmental consultants performing similar work in the project area. No other warranty, expressed or implied, is made regarding the professional opinions presented in this report. Variations in site conditions may exist and conditions not observed or described in this report may be encountered during subsequent activities. Please also note that this study did not include an evaluation of geotechnical conditions or potential geologic hazards.

---

This document is intended to be used only in its entirety. No portion of the document, by itself, is designed to completely represent any aspect of the project described herein. Ninyo & Moore should be contacted if the reader requires any additional information, or has questions regarding content, interpretations presented, or completeness of this document.

The environmental interpretations and opinions contained in this report are based on the results of laboratory tests and analyses intended to detect the presence of ACMs in samples collected from the subject site. The testing and analyses have been conducted by an independent laboratory, which is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP), for bulk asbestos fiber analysis. Ninyo & Moore has no involvement in, or control over, such testing and analysis. Ninyo & Moore, therefore, disclaims responsibility for any inaccuracy in such laboratory results.


Our conclusions, recommendations, and opinions are based on an analysis of the observed site conditions. It should be understood that the conditions of a site could change with time as a result of natural processes or the activities of man at the subject site or nearby sites. In addition, changes to the applicable laws, regulations, codes, and standards of practice may occur due to government action or the broadening of knowledge. The findings of this report may, therefore, be invalidated over time, in part or in whole, by changes over which Ninyo & Moore has no control.

Silver Strike Motel  
201 North Main Street  
Tonopah, Nevada

March 31, 2003  
Project No. 301218001

---

**FIGURES**



REFERENCE: USGS, TONOPAH QUADRANGLE, NEVADA, 7.5 MINUTE SERIES (Topographic): dated 1982.



NORTH

0 2000  
Approximate Scale in Feet

## SITE LOCATION MAP


HAZARDOUS BUILDING MATERIALS SURVEY  
SILVER STRIKE MOTEL  
201 MAIN STREET  
TONOPAH, NEVADA

PROJECT NO.  
301218001

DATE  
03/2003

FIGURE  
1


**Ninjo & Moore**



#### LEGEND

- Subject site (dashed line)
- AST  Aboveground storage tank

NOTE: All dimensions and directions are approximate.



**Ninjo & Moore**

#### SITE AND VICINITY MAP

HAZARDOUS BUILDING MATERIALS SURVEY  
SILVER STRIKE MOTEL  
201 MAIN STREET \TONOPAH, NEVADA

PROJECT NO.

301218001


DATE

03/2003

FIGURE

2

ST. PATRICK STREET




MAIN STREET (Highway 95)

LEGEND

- Sample location

NOTE: All dimensions and directions are approximate.



**Ninyo & Moore**

SAMPLE LOCATION MAP  
BUILDING NO. 1


HAZARDOUS BUILDING MATERIALS SURVEY  
SILVER STRIKE MOTEL  
201 MAIN STREET \TONOPAH, NEVADA

PROJECT NO.  
301218001

DATE  
03/2003

FIGURE  
3


ST. PATRICK STREET



LEGEND

- Sample location
- X Indicates roof sample

NOTE: All dimensions and directions are approximate.



**Ninjo & Moore**



SAMPLE LOCATION MAP  
BUILDING NO. 2

HAZARDOUS BUILDING MATERIALS SURVEY  
SILVER STRIKE MOTEL  
201 MAIN STREET \TONOPAH, NEVADA

PROJECT NO.  
301218001

DATE  
03/2003

FIGURE  
4



0 20  
APPROXIMATE SCALE IN FEET

NOTE: All dimensions and directions are approximate.

**Ninyo & Moore**

### SAMPLE LOCATION MAP BUILDING NO. 3

HAZARDOUS BUILDING MATERIALS SURVEY  
SILVER STRIKE MOTEL  
201 MAIN STREET \TONOPAH, NEVADA

PROJECT NO.

301218001




DATE

03/2003

FIGURE

5


CENTRAL STREET



LEGEND

- Sample location

NOTE: All dimensions and directions are approximate.



0 20  
APPROXIMATE SCALE IN FEET

**Ninjo & Moore**

SAMPLE LOCATION MAP  
BUILDING NO. 4

HAZARDOUS BUILDING MATERIALS SURVEY  
SILVER STRIKE MOTEL  
201 MAIN STREET \TONOPAH, NEVADA

PROJECT NO.

301218001


DATE

03/2003

FIGURE

6


CENTRAL STREET



LEGEND

- Sample location
- X Indicates roof sample

NOTE: All dimensions and directions are approximate.



SAMPLE LOCATION MAP  
BUILDING NO. 5

HAZARDOUS BUILDING MATERIALS SURVEY  
SILVER STRIKE MOTEL  
201 MAIN STREET \TONOPAH, NEVADA

**Ninyo & Moore**

PROJECT NO.


301218001

DATE

03/2003

FIGURE


7



**LEGEND**

- Sample location
- X Indicates roof sample

NOTE: All dimensions and directions are approximate.



**Ninjo & Moore**

**SAMPLE LOCATION MAP  
POOL**

**HAZARDOUS BUILDING MATERIALS SURVEY  
SILVER STRIKE MOTEL  
201 MAIN STREET \TONOPAH, NEVADA**

PROJECT NO.	DATE
301218001	03/2003

**FIGURE  
8**

Silver Strike Motel  
201 North Main Street  
Tonopah, Nevada

March 31, 2003  
Project No. 301218001

---

**TABLES**

**Table 1 - Asbestos Survey Results**

Sample No.	Bldg No.	Layer	Sample Location	Sample Description	Reable VIN	Condition	Asbestos Content
B-001	1	1	Unit 2 - Wall System	Wall Plaster, Beige	Y	Good	ND
		2	Unit 2 - Wall System	Wall Texture, White	Y	Good	ND
		3	Unit 2 - Wall System	Wallboard, Tan	Y	Good	ND
B-002	1	1	Unit 2 - Wall System	Wall Plaster, Beige	N	Good	ND
		2	Unit 2 - Wall System	Wall Texture, White	N	Good	ND
		3	Unit 2 - Wall System	Joint Compound, Beige	N	Good	2% Chrysotile
B-003	1	1	NE Corner, Exterior Wall	Exterior Stucco, Beige	N	Good	ND
B-004	1	1	Unit 3, Bedroom	9"x9" Floor Tile, Red, Brown	N	Good	10% Chrysotile
	1	2	Unit 3, Bedroom	Mastic, Black	N	Good	10% Chrysotile
	1	1	Unit 1, Bedroom	9"x9" Floor Tile, Gray	N	Good	10% Chrysotile
B-005	1	2	Unit 1, Bedroom	Mastic, Black	N	Good	10% Chrysotile
	1	1	Unit 1, Bathroom	Vinyl Sheet Flooring, Tan	Y	Good	20% Chrysotile
B-006	1	2	Unit 1, Bathroom	Mastic, Tan	Y	Good	2% Chrysotile
	1	1	Unit 3, Bathroom	Vinyl Sheet Flooring, Brown	Y	Good	ND
B-007	1	2	Unit 3, Bathroom	Mastic, Tan	Y	Good	ND
	1	1	Unit 4, Wall System	Wall Plaster, Beige	Y	Good	ND
B-008	1	2	Unit 4, Wall System	Wall Texture, White	Y	Good	ND
	1	3	Unit 4, Wall System	Wallboard, Tan	Y	Good	ND
	1	1	Unit 4, Shower Stall	Shower Wall, White, Brown	N	Good	ND
B-009	1	2	Unit 4, Shower Stall	Mastic, Red	N	Good	ND
	1	1	Unit 3, Bathroom	Ceramic Tile, Red/White	N	Good	ND
B-010	1	2	Unit 3, Bathroom	Grout, Off-White	N	Good	ND
	1	3	Unit 3, Bathroom	Mastic, Tan/Black	N	Good	10% Chrysotile

Table 1 - Asbestos Survey Results

Sample No.	Bldg. No.	Layer	Sample Location	Sample Description	Friable X/N	Condition	Asbestos Content
B-011	1	1	SW Corner, Exterior Wall	Exterior Stucco Scratch Coat, Beige	N	Good	ND
	1	2	SW Corner, Exterior Wall	Exterior Stucco Finish Coat, White/Pink	N	Good	ND
	1	3	SW Corner, Exterior Wall	Concrete Bricks, Beige, White	N	Good	ND
B-012	1	1	Unit 3, Bathroom	Wall Plaster, Beige	N	Good	ND
	1	2	Unit 3, Bathroom	Wall Texture, White	N	Good	ND
	2	1	Unit 7, Wall System	Wall Plaster, Beige	Y	Good	ND
B-013	2	2	Unit 7, Wall System	Wall Texture, White	Y	Good	ND
	2	3	Unit 7, Wall System	Wallboard, Tan	Y	Good	ND
	2	1	Unit 8, Ceiling	Drywall, Brown/Off-White	Y	Good	ND
B-014	2	2	Unit 8, Ceiling	Texture, White	Y	Good	2% Chrysotile
	2	1	Unit 10, Bathroom	Ceramic Tile, Gray/White	N	Good	ND
	2	2	Unit 10, Bathroom	Grout, Gray	N	Good	ND
B-015	2	3	Unit 10, Bathroom	Grout, Beige	N	Good	ND
	2	1	Unit 9, Bedroom	Drywall, Brown/Off-White	N	Good	ND
	2	2	Unit 9, Bedroom	Joint Compound, White	N	Good	ND
B-016	2	1	Unit 10, Bedroom	Wall Plaster, Beige	Y	Good	ND
	3	1	Bldg. 3 Office - Kitchen Area	Vinyl Sheet Flooring, Brown, Tan	Y	Good	20% Chrysotile
	3	2	Bldg. 3 Office - Kitchen Area	Mastic, Tan	Y	Good	2% Chrysotile
B-017	3	1	Unit 19, Bedroom	Drywall, Brown/Off-White	N	Damaged	ND
	3	2	Unit 19, Bedroom	Joint Compound, White	N	Damaged	2% Chrysotile
	3	3	Unit 19, Bedroom	Texture, White	N	Damaged	3% Chrysotile
B-018	3	1	Unit 19, Bedroom	Ceiling Tile, White/Tan	Y	Damaged	ND
	3	1	Unit 28, Bedroom	Drywall, Brown/Off-White	N	Damaged	ND
	3	2	Unit 28, Bedroom	Joint Compound, White	N	Damaged	2% Chrysotile

Silv like N  
201 North Main Street  
Tonopah, Nevada

Y-31,  
Project No. 301218001

Table 1 - Asbestos Survey Results

Sample No.	Bldg. No.	Layer	Sample Location	Sample Description	Friable V/N	Condition	Asbestos Content
B-022	3	1	Unit 28, Bedroom	Ceiling Tile, White/Tan	Y	Damaged	ND
B-023	3	1	Unit 20, Restroom	Vinyl Sheet Flooring, Tan/White	Y	Good	20% Chrysotile
B-023	3	2	Unit 20, Restroom	Mastic, Tan	Y	Good	2% Chrysotile
B-024	3	1	Unit 20, Bedroom	Ceiling Tile, White/Tan	Y	Damaged	ND
B-024	3	1	Office, Main Office	9"x9" Vinyl Floor Tile, Brown	N	Good	3% Chrysotile
B-025	3	2	Office, Main Office	Mastic, Black	N	Good	10% Chrysotile
B-026	3	1	Unit 18, Restroom	12"x12" Vinyl Floor Tile, White, Gray	N	Good	ND
B-026	3	2	Unit 18, Restroom	Mastic, White, Silver	N	Good	ND
B-027	3	1	Unit 19, Restroom	Vinyl Floor Tile, White, Gray	N	Good	15% Chrysotile
B-027	3	2	Unit 19, Restroom	Mastic, Black, Brown	N	Good	2% Chrysotile
B-028	3	1	Unit 27, Restroom	Vinyl Floor Tile, White, Gold	Y	Good	5% Chrysotile
B-028	3	2	Unit 27, Restroom	Mastic, Yellow	Y	Good	ND
B-028	3	3	Unit 27, Restroom	Vinyl Sheet Flooring, Beige	Y	Good	15% Chrysotile
B-028	3	4	Unit 27, Restroom	Mastic, Brown	Y	Good	2% Chrysotile
B-029	3	1	Unit 17, Restroom	Vinyl Sheet Flooring, Brown	Y	Good	ND
B-029	3	2	Unit 17, Restroom	Mastic, Yellow	Y	Good	3% Chrysotile
B-030	3	3	Unit 17, Restroom	Leveling Compound, White	Y	Damaged	ND
B-030	3	1	Unit 12, Bedroom	Textured Ceiling Tile, White, Yellow	Y	Good	ND
B-031	3	1	Unit 12, Bedroom	Vinyl Sheet Flooring, Brown	Y	Good	ND
B-031	3	2	Unit 12, Bedroom	Mastic, Brown	Y	Good	ND
B-031	3	3	Unit 12, Bedroom	Vinyl Sheet Flooring, Gray, Black	Y	Good	15% Chrysotile
B-031	3	4	Unit 12, Bedroom	Mastic, Brown	Y	Good	2% Chrysotile

Table 1 - Asbestos Survey Results

Sample No.	Bldg No.	Layer	Sample Location	Sample Description	Friable VS/N	Condition	Asbestos Content
B-032	3	1	Unit 23, Restroom	Vinyl Sheet Flooring, White/Lt. Green	Y	Good	5% Chrysotile
	3	2	Unit 23, Restroom	Mastic, Brown	Y	Good	2% Chrysotile
	3	3	Unit 23, Restroom	Felt, Black	Y	Good	ND
	3	1	Unit 23, Bedroom	Ceiling Tile, White/Yellow	Y	Damaged	ND
B-034	4	1	Unit 35, Bedroom	28"x16" Ceiling Tile, White/Yellow	Y	Damaged	ND
	4	1	Unit 35, Restroom	Drywall, White, Brown	N	Damaged	ND
	4	2	Unit 35, Restroom	Joint Compound, White	N	Damaged	2% Chrysotile
	4	3	Unit 35, Restroom	Texture, White	N	Damaged	2% Chrysotile
B-035	4	1	Unit 35, Restroom Ceiling	12"x12" Vinyl Floor Tile, Gray	N	Good	ND
	4	2	Unit 35, Restroom Ceiling	Mastic, Yellow	N	Good	ND
	4	3	Unit 35, Restroom Ceiling	Backing, Brown	N	Good	ND
	4	1	Unit 38, Restroom	Drywall, White, Brown	N	Damaged	ND
B-036	4	2	Unit 35, Restroom Ceiling	Joint Compound, White	N	Damaged	ND
	4	3	Unit 35, Restroom Ceiling	Texture, White	N	Damaged	ND
	4	1	Unit 38, Restroom	12"x12" Vinyl Floor Tile, Gray	N	Good	ND
	4	2	Unit 38, Restroom	Mastic, Yellow	N	Good	ND
B-037	4	2	Unit 38, Restroom	Joint Compound, White	N	Damaged	ND
	4	3	Unit 38, Restroom	Texture, White	N	Damaged	ND
	4	1	Unit 38, Restroom	12"x12" Vinyl Floor Tile, Gray	N	Good	ND
	4	2	Unit 38, Restroom	Mastic, Yellow	N	Good	ND
B-038	4	1	Unit 39, Bedroom Ceiling	Joint Compound, White/Yellow	Y	Damaged	ND
	4	2	Unit 39, Bedroom Ceiling	Texture, White	Y	Damaged	ND
	4	1	Unit 39, Bedroom Ceiling	Drywall, White, Brown	Y	Damaged	ND
	4	2	Unit 39, Bedroom Ceiling	Joint Compound, White	Y	Damaged	3% Chrysotile
B-041	2	1	Unit 10, Bedroom Ceiling	Texture/Paint, White	Y	Damaged	2% Chrysotile
	2	2	Unit 10, Bedroom Ceiling				
	2	3	Unit 10, Bedroom Ceiling				

Table 1 - Asbestos Survey Results

Sample No.	Bldg No.	Layer	Sample Location	Sample Description	Possible X/N	Condition	Asbestos Content
B-042	2	1	Roof	Roof Material, White, Black	N	Good	30% Chrysotile
	2	2	Roof	Roof Mastic, Black	N	Good	ND
	2	3	Roof	Roof Mastic, Black	N	Good	ND
B-043	2	1	Roof	Roof Mastic, Gray, Black	N	Good	ND
B-044	2	1	Roof	Vent Pipe, Beige, White	N	Good	20% Chrysotile 2% Crocidolite
B-045	2	1	Roof Awning	Asphalt Shingle, White, Black	N	Good	ND
B-046	P	1	Pool	Pool Wall Material, White/Beige	N	Good	ND
B-047	P	1	Pool	Pool Concrete Edging, White/Tan	N	Good	ND
B-048	P	1	Pool House Roof	Asphalt Shingle, White, Black	N	Good	ND
	P	2	Pool House Roof	Felt, Black	N	Good	ND
	5	1	Mechanical Room Roof	Rolled Roofing, Black/Orange/Beige	N	Good	ND
B-049	5	2	Mechanical Room Roof	Rolled Roofing, Silver/Black	N	Good	ND
	5	3	Mechanical Room Roof	Rolled Roofing, Black	N	Good	5% Chrysotile
B-050	5	1	Unit 3, Bedroom Wall	Drywall, White, Brown	N	Good	ND
	5	2	Unit 3, Bedroom Wall	Joint Compound, White	N	Good	ND
B-051	5	1	Unit 3, Utility Room	12"x12" Vinyl Floor Tile, White, Gray	N	Good	ND
	5	2	Unit 3, Utility Room	Mastic, Yellow	N	Good	ND
B-052	5	1	Unit 3, Restroom Shower Wall	Ceramic Tile, White/Red	N	Good	ND
	5	2	Unit 3, Restroom Shower Wall	Mortar, Gray	N	Good	<1% Chrysotile
B-053	5	1	Unit 5, Bedroom Wall	Drywall, White, Brown	N	Good	ND
	5	2	Unit 5, Bedroom Wall	Joint Compound, White	N	Good	3% Chrysotile
B-054	5	1	Unit 5, Utility Room	12"x12" Vinyl Floor Tile, White, Gray	N	Good	ND
	5	2	Unit 5, Utility Room	Mastic, Yellow	N	Good	ND

**Table 1 - Asbestos Survey Results**

Sample No.	Bldg No.	Layer	Sample Location	Sample Description	Friable Y/N	Condition	Asbestos Content
B-055	5	1	Unit 5, Bedroom Ceiling	Drywall, White, Brown	N	Good	ND
	5	2	Unit 5, Bedroom Ceiling	Joint Compound, White	N	Good	3% Chrysotile
B-056	5	1	Unit 7, Restroom Wall	Drywall, White, Brown	N	Good	ND
	5	2	Unit 7, Restroom Wall	Joint Compound, White	N	Good	3% Chrysotile
B-057	5	1	Unit 7, Restroom	12"x12" Vinyl Floor Tile, White, Gray	N	Good	ND
	5	2	Unit 7, Restroom	Mastic, Yellow	N	Good	ND
B-058	5	1	Unit 9, Bedroom Wall	Drywall, White, Brown	N	Good	ND
	5	2	Unit 9, Bedroom Wall	Joint Compound, White	N	Good	3% Chrysotile
	5	1	Roof	Rolled Roofing, Black/Orange/Beige	N	Good	ND
B-059	5	2	Roof	Rolled Roofing, Black/Gray	N	Good	15% Chrysotile
	5	3	Roof	Rolled Roofing, Black	N	Good	ND
B-060	5	1	Roof	Roofing Mastic, Black	N	Good	10% Chrysotile
B-061	4	1	Unit 48, Restroom	Drywall, White, Brown	N	Damaged	ND
	4	2	Unit 48, Restroom	Joint Compound, White	N	Damaged	ND
B-062	4	1	Unit 48, Restroom	12"x12" Vinyl Floor Tile, White/Gray	N	Good	ND
	4	2	Unit 48, Restroom	Mastic, Tan	N	Good	ND
B-063	4	1	Unit 49, Bedroom	28"x16" Ceiling Tile, White/Tan	Y	Damaged	ND
	4	1	Unit 49, Bedroom	Drywall, Brown/Off-White	N	Damaged	ND
B-064	4	2	Unit 49, Bedroom	Joint Compound, White	N	Damaged	ND
	4	1	Unit 50, Restroom	Drywall, Brown/Off-White	N	Damaged	ND
B-065	4	2	Unit 50, Restroom	Joint Compound, White	N	Damaged	ND
	4	1	Managers Apartment, Roof	Asphalt Shingle Roof, Beige, Black	N	Good	ND
B-066	4	2	Managers Apartment, Roof	Asphalt Shingle Roof, Felt, Black	N	Good	ND
	4	1	Managers Apartment, Roof	Roofing Mastic, Black	N	Good	ND

Table 1 - Asbestos Survey Results

Sample No.	Blkt No.	Layer	Sample Location	Sample Description	Friable Y/N	Condition	Asbestos Content
B-068	4	1	Managers Apartment, Entrance	Drywall, Brown/Off-White	N	Damaged	ND
		2	Managers Apartment, Entrance	Joint Compound, White	N	Damaged	3% Chrysotile
B-069	4	1	Managers Apartment, Living Room	Ceiling Tile, White/Tan, Grooved	Y	Damaged	ND
		1	Managers Apartment, Family Room	Vinyl Sheet Flooring, Tan	Y	Good	20% Chrysotile
B-070	4	2	Managers Apartment, Family Room	Mastic, Tan	Y	Good	3% Chrysotile

**NOTES:**

SF=Square Feet

EA=Each

ND=None Detected

N/A=Not Applicable

LF=Linear Feet

Silver Strike Motel  
201 North Main Street  
Tonopah, Nevada

March 31, 2003  
Project # 301218001

TABLE 2  
SUMMARY OF PAINT CHIP ANALYTICAL RESULTS

Field Sample No.	Building & Location	Component	Color	Total Lead PPM
PC-001	Bldg. 1, Unit 2	Plaster	Tan	1487
PC-002	Bldg. 1, Unit 5	Wood	Blue	2662
PC-003	Bldg. 1, SE Corner	Stucco	Pink	BRL *
PC-004	Bldg. 1, Unit 1 - Exterior	Wood	Dark Gray	131
PC-005	Bldg. 2, Unit 10 - Exterior	Wood	Light Blue	BRL
PC-006	Bldg. 3, Exterior Under Balcony	Wood	White	BRL
PC-007	Bldg. 3, 2nd Floor-Exterior Balcony Ceiling	Wood	White	119
PC-008	Bldg. 4, Unit 34 Restroom	Drywall	White	BRL
PC-009	Bldg. 4, Unit 35 - Exterior	Wood	Blue	788
PC-010	Bldg. 4, unit 36 - Exterior	Wood	Pink	193
PC-011	Bldg. 4, Unit 37 - Exterior	Wood	White	BRL
PC-012	Bldg. 3, Stair Railing(2)	Metal	White	BRL
PC-013	Pool, Siding - SE Corner	Concrete	Blue	558
PC-014	Bldg. 5, Unit 6	Wood	Pink	994
PC-015	Bldg. 5, Unit 6	Wood	Blue	405
PC-016	Bldg. 5, Unit 4	Wood	Dark Blue	279
PC-017	Bldg. 4, Unit 43	Wood	Pink	195
PC-018	Bldg. 4, Unit 44	Wood	Blue	BRL
PC-019	Bldg. 4, Unit 45	Wood	White	1124

NOTES:

Total Lead analyzed by EPA Test Method 8270.

ND = Not detected at the reported detection limit.

PPM = Parts Per Million also known as mg/kg (milligrams per kilogram)

BRL = Below reportable limits

\* = Excessive substrate may bias sample results

Silver Strike Motel  
201 N. Main Street  
Tonopah, Nevada

March 31, 2003  
Project No. 301218001

Table 3 - Summary of Hazardous Building Materials

Material Location	Transformers	Number of Light Ballast	Number of Thermostats/ Switches	Number of A/C Units	Fluorescent light tubes	Number of Exit Signs	Miscellaneous
Building 1	0	18	0	9	18	0	0
Building 2	0	0	0	1	0	0	0
Building 3	0	2	0	10	15	0	1-Refrigerator
Building 4	0	8	0	14	8	0	1-Lead-acid Battery
Building 5	0	0	0	7	0	0	

NOTES:  
A/C = Air Conditioning

Nye County Grants Administrative Office  
Silver Strike Motel, Tonopah, Nevada

March 31, 2003  
Project No. 301218001

---

**APPENDIX H**

**Asbestos and Lead-based Paint Laboratory Reports**  
**And Chain of Custody Records**

# EMC LABS, INC.

Laboratory Report

0009557

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044  
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

## Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	NINYO & MOORE	Job# / P.O. #:	301218001
Address:	3155 E. PATRICK LANE, STE 12	Date Received:	03/12/2003
	LAS VEGAS NV 89120	Date Analyzed:	03/12/2003
Collected:	03/06/2003	Date Reported:	03/12/2003
Project Name/	TONOPAH/PINK MOTEL	EPA Method:	EPA 600/M4-82-020
Address:	201 MAIN STREET	Submitted By:	ROBERT TROISI
		Collected By:	Customer

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0009557-001 B-01	BLDG 1-UNIT 2 WALL SYSTEM	LAYER# 1 Wall Plaster, Beige	No		Quartz Gypsum Mica Binder/Filler 100%
		LAYER# 2 Wall Texture, White	No		Cellulose Fiber <1% Carbonates Gypsum Mica Binder/Filler
		LAYER# 3 Wallboard, Tan	No		Cellulose Fiber 95% Binder/Filler 5%
0009557-002 B-02	BLDG 1-UNIT 2 WALL SYSTEM	LAYER# 1 Wall Plaster, Beige	No		Quartz Gypsum Mica Binder/Filler 100%
		LAYER# 2 Wall Texture, White	No		Cellulose Fiber <1% Carbonates Gypsum Mica Binder/Filler
		LAYER# 3 Joint Compound, Beige	Yes	Chrysotile 2%	Carbonates Mica Quartz Binder/Filler 98%
0009557-003 B-03	NE CORNER BLDG #1 EXT. WALL	Exterior Stucco, Beige	No		Quartz Gypsum Carbonates Mica Binder/Filler 100%

# EMC LABS, INC.

Laboratory Report

0009557

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044  
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

## Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	NINYO & MOORE	Job# / P.O. #:	301218001
Address:	3155 E. PATRICK LANE, STE 12 LAS VEGAS NV 89120	Date Received:	03/12/2003
Collected:	03/06/2003	Date Analyzed:	03/12/2003
Project Name/	TONOPAH/PINK MOTEL	Date Reported:	03/12/2003
Address:	201 MAIN STREET	EPA Method:	EPA 600/M4-82-020
		Submitted By:	ROBERT TROISI
		Collected By:	Customer

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0009557-004 B-04	BLDG 1 UNIT 3 BEDRM	LAYER# 1 9x9 Floor Tile, Red/Brown	Yes	Chrysotile 10%	Carbonates Gypsum Mica Quartz Binder/Filler 90%	
		LAYER# 2 Mastic, Black	Yes	Chrysotile 10%	Carbonates Binder/Filler 90%	
0009557-005 B-05	BLDG 1 UNIT 1 BEDRM	LAYER# 1 9x9 Floor Tile, Gray	Yes	Chrysotile 10%	Carbonates Gypsum Quartz Mica Binder/Filler 90%	
		LAYER# 2 Mastic, Black	Yes	Chrysotile 10%	Cellulose Fiber Carbonates Binder/Filler 89%	
0009557-006 B-06	BLDG 1 UNIT 1 BATHRM	LAYER# 1 Vinyl Sheet Flooring, Tan	Yes	Chrysotile 20%	Cellulose Fiber Gypsum Carbonates Binder/Filler 78%	
		LAYER# 2 Mastic, Tan Note: Difficult to separate adjacent layers	Yes	Chrysotile 2%	Gypsum Binder/Filler 98%	

# EMC LABS, INC.

Laboratory Report

0009557

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044  
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

## Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	NINYO & MOORE	Job# / P.O. #:	301218001
Address:	3155 E. PATRICK LANE, STE 12	Date Received:	03/12/2003
	LAS VEGAS NV 89120	Date Analyzed:	03/12/2003
Collected:	03/06/2003	Date Reported:	03/12/2003
Project Name/	TONOPAH/PINK MOTEL	EPA Method:	EPA 600/M4-82-020
Address:	201 MAIN STREET	Submitted By:	ROBERT TROISI
		Collected By:	Customer

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0009557-007 B-07	BLDG 1 UNIT 3 BATHRM	LAYER# 1 Vinyl Sheet Flooring, Brown	No		Cellulose Fiber Fibrous Glass  Gypsum Perlite Quartz Binder/Filler	20% 2%  78%
		LAYER# 2 Mastic, Tan	No		Cellulose Fiber Gypsum Binder/Filler	2% 98%
0009557-008 B-08	BLDG 1 UNIT 4 WALL SYSTEM	LAYER# 1 Wall Plaster, Beige	No		Quartz Gypsum Mica Binder/Filler	100%
		LAYER# 2 Wall Texture, White	No		Gypsum Carbonates Mica Quartz Binder/Filler	100%
		LAYER# 3 Wallboard, Tan	No		Cellulose Fiber Binder/Filler	95% 5%
0009557-009 B-09	BLDG 1 UNIT 4 SHOWER STALL	LAYER# 1 Shower Wall, White, Brown	No		Cellulose Fiber  Gypsum Binder/Filler	80% 20%
		LAYER# 2 Mastic, Red	No		Cellulose Fiber Gypsum Binder/Filler	2% 98%

# EMC LABS, INC.

Laboratory Report

0009557

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044  
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

## Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	NINYO & MOORE	Job# / P.O. #:	301218001
Address:	3155 E. PATRICK LANE, STE 12	Date Received:	03/12/2003
	LAS VEGAS NV 89120	Date Analyzed:	03/12/2003
Collected:	03/06/2003	Date Reported:	03/12/2003
Project Name/	TONOPAH/PINK MOTEL	EPA Method:	EPA 600/M4-82-020
Address:	201 MAIN STREET	Submitted By:	ROBERT TROISI
		Collected By:	Customer

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0009557-010 B-010	BLDG 1 UNIT 3 BATHRM	LAYER# 1 Ceramic Tile, Red/ White	No		Gypsum Quartz Binder/Filler	100%
		LAYER# 2 Grout, Off White	No		Carbonates Gypsum Binder/Filler	100%
		LAYER# 3 Mastic, Tan/ Black	Yes	Chrysotile 10%	Gypsum Carbonates Binder/Filler	90%
0009557-011 B-011	SW CORNER BLDG 1 EXT. WALL	LAYER# 1 Ext. Stucco-Scratch Coat, Beige	No		Quartz Gypsum Mica Binder/Filler	100%
		LAYER# 2 Ext. Stucco-Finish Coat, White/ Pink	No		Quartz Gypsum Mica Binder/Filler	100%
		LAYER# 3 Concrete Bricks, Beige, White	No		Carbonates Perlite Quartz Binder/Filler	100%

# EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044  
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report  
**0009557**

## Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	NINYO & MOORE	Job# / P.O. #:	301218001
Address:	3155 E. PATRICK LANE, STE 12 LAS VEGAS NV 89120	Date Received:	03/12/2003
Collected:	03/06/2003	Date Analyzed:	03/12/2003
Project Name/	TONOPAH/PINK MOTEL	Date Reported:	03/12/2003
Address:	201 MAIN STREET	EPA Method:	EPA 600/M4-82-020
		Submitted By:	ROBERT TROISI
		Collected By:	Customer

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0009557-012 B-012	BLDG 1 UNIT 3 BATHRM	LAYER# 1 Wall Plaster, Beige Note: No Joint Compound Present	No		Quartz Gypsum Mica Binder/Filler	100%
		LAYER# 2 Wall Texture, White	No		Cellulose Fiber Gypsum Carbonates Mica Quartz Binder/Filler	<1% 99%
0009557-013 B-013	BLDG 2 UNIT 7 WALL SYSTEM	LAYER# 1 Wall Plaster, Beige	No		Quartz Gypsum Mica Binder/Filler	100%
		LAYER# 2 Wall Texture, White	No		Quartz Gypsum Mica Binder/Filler	100%
		LAYER# 3 Wallboard, Tan	No		Cellulose Fiber Gypsum Carbonates Mica Quartz Binder/Filler	10% 90%

# EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044  
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report  
**0009557**

## Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	NINYO & MOORE	Job# / P.O. #:	301218001
Address:	3155 E. PATRICK LANE, STE 12 LAS VEGAS NV 89120	Date Received:	03/12/2003
Collected:	03/06/2003	Date Analyzed:	03/12/2003
Project Name/	TONOPAH/PINK MOTEL	Date Reported:	03/12/2003
Address:	201 MAIN STREET	EPA Method:	EPA 600/M4-82-020
		Submitted By:	ROBERT TROISI
		Collected By:	Customer

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0009557-014 B-014	BLDG 2 UNIT 8 CEILING	LAYER# 1 Drywall, Brown/ Off White	No		Cellulose Fiber Gypsum Carbonates Mica Quartz Binder/Filler	10%
		LAYER# 2 Texture, White	Yes	Chrysotile 2%	Carbonates Mica Quartz Binder/Filler	90%
0009557-015 B-015	BLDG 2 UNIT 10 BATHRM	LAYER# 1 Ceramic Tile, Gray/ White	No		Gypsum Quartz Binder/Filler	100%
		LAYER# 2 Grout, Gray	No		Quartz Gypsum Carbonates Mica Binder/Filler	100%
		LAYER# 3 Grout, Beige	No		Quartz Gypsum Carbonates Mica Binder/Filler	100%

# EMC LABS, INC.

Laboratory Report

0009557

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044  
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

## Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	NINYO & MOORE	Job# / P.O. #:	301218001
Address:	3155 E. PATRICK LANE, STE 12 LAS VEGAS NV 89120	Date Received:	03/12/2003
Collected:	03/06/2003	Date Analyzed:	03/12/2003
Project Name/	TONOPAH/PINK MOTEL	Date Reported:	03/12/2003
Address:	201 MAIN STREET	EPA Method:	EPA 600/M4-82-020
		Submitted By:	ROBERT TROISI
		Collected By:	Customer

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0009557-016 B-016	BLDG 2 UNIT 9 BEDRM	LAYER# 1 Drywall, Brown/ Off White	No		Cellulose Fiber Gypsum Carbonates Mica Quartz Binder/Filler	10% 90%
		LAYER# 2 Joint Compound, White	No		Carbonates Gypsum Mica Binder/Filler	100%
0009557-017 B-017	BLDG 2 UNIT 10 BEDRM	Wall Plaster, Beige	No		Quartz Gypsum Carbonates Mica Binder/Filler	100%
0009557-018 B-018	BLDG 3 OFFICE KITCHEN AREA	LAYER# 1 Vinyl Sheet Flooring, Brown, Tan	Yes	Chrysotile 20%	Cellulose Fiber Gypsum Binder/Filler	2% 78%
		LAYER# 2 Mastic, Tan	Yes	Chrysotile 2%	Cellulose Fiber Gypsum Binder/Filler	1% 97%

# EMC LABS, INC.

Laboratory Report

0009557

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044  
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

## Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	NINYO & MOORE	Job# / P.O. #:	301218001
Address:	3155 E. PATRICK LANE, STE 12	Date Received:	03/12/2003
	LAS VEGAS NV 89120	Date Analyzed:	03/12/2003
Collected:	03/06/2003	Date Reported:	03/12/2003
Project Name/	TONOPAH/PINK MOTEL	EPA Method:	EPA 600/M4-82-020
Address:	201 MAIN STREET	Submitted By:	ROBERT TROISI
		Collected By:	Customer

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0009557-019 B-019	BLDG 3 UNIT 19 BEDRM	LAYER# 1 Drywall, Brown/ Off White	No		Cellulose Fiber	10%
					Gypsum Carbonates Mica Quartz Binder/Filler	90%
		LAYER# 2 Joint Compound, White	Yes	Chrysotile 2%	Cellulose Fiber Carbonates Mica Quartz Binder/Filler	<1%
						97%
		LAYER# 3 Texture, White	Yes	Chrysotile 3%	Carbonates Mica Quartz Binder/Filler	97%
0009557-020 B-020	BLDG 3 UNIT 19 BEDRM	Ceiling Tile, White/ Tan	No		Cellulose Fiber	95%
					Binder/Filler	5%
0009557-021 B-021	BLDG 3 UNIT 28 BEDRM	LAYER# 1 Drywall, Brown/ Off White	No		Cellulose Fiber	10%
					Gypsum Carbonates Mica Binder/Filler	90%
		LAYER# 2 Joint Compound, White Note: Very small amount of sample- may effect analysis	Yes	Chrysotile 2%	Cellulose Fiber Carbonates Mica Binder/Filler	<1%
						97%
0009557-022 B-022	BLDG 3 UNIT 28 BEDRM	Ceiling Tile, White/ Tan	No		Cellulose Fiber	95%
					Carbonates Binder/Filler	5%

# EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044  
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report  
**0009557**

## Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	NINYO & MOORE	Job# / P.O. #:	301218001
Address:	3155 E. PATRICK LANE, STE 12 LAS VEGAS NV 89120	Date Received:	03/12/2003
Collected:	03/06/2003	Date Analyzed:	03/12/2003
Project Name/	TONOPAH/PINK MOTEL	Date Reported:	03/12/2003
Address:	201 MAIN STREET	EPA Method:	EPA 600/M4-82-020
		Submitted By:	ROBERT TROISI
		Collected By:	Customer

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0009557-023 B-023	BLDG 3 UNIT 20 RESTRM	LAYER# 1 Vinyl Sheet Flooring, Tan/ White  LAYER# 2 Mastic, Tan Note: Difficult to separate adjacent layers	Yes	Chrysotile  Chrysotile	20%  Gypsum Binder/Filler 80%
0009557-024 B-024	BLDG 3 UNIT 20 BEDRM	Ceiling Tile, White/ Tan	No		Cellulose Fiber  Carbonates Binder/Filler 10%
0009557-025 B-025	BLDG 3 OFFICE MAIN OFFICE	LAYER# 1 9x9 Vinyl Floor Tile, Brown  LAYER# 2 Mastic, Black	Yes	Chrysotile  Chrysotile	3%  Carbonates Gypsum Quartz Mica Binder/Filler 97%  Carbonates Binder/Filler 90%
0009557-026 B-026	BLDG 3 UNIT 18 RESTRM	LAYER# 1 12x12 Vinyl Floor Tile, White, Gray  LAYER# 2 Mastic, White, Silver	No		Carbonates Quartz Binder/Filler 100%  Carbonates Gypsum Quartz Binder/Filler 100%

# EMC LABS, INC.

Laboratory Report

0009557

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044  
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

## Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	NINYO & MOORE	Job# / P.O. #:	301218001
Address:	3155 E. PATRICK LANE, STE 12 LAS VEGAS NV 89120	Date Received:	03/12/2003
Collected:	03/06/2003	Date Analyzed:	03/12/2003
Project Name/	TONOPAH/PINK MOTEL	Date Reported:	03/12/2003
Address:	201 MAIN STREET	EPA Method:	EPA 600/M4-82-020
		Submitted By:	ROBERT TROISI
		Collected By:	Customer

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0009557-027 B-027	BLDG 3 UNIT 19 RESTRM	LAYER# 1 Vinyl Floor Tile, White, Gray	Yes	Chrysotile 15%	Carbonates Gypsum Binder/Filler	85%
		LAYER# 2 Mastic, Black, Brown Note: Difficult to separate adjacent layers	Yes	Chrysotile 2%	Carbonates Gypsum Binder/Filler	98%
0009557-028 B-028	BLDG 3 UNIT 27 RESTRM	LAYER# 1 Vinyl Floor Tile, White/ Gold	Yes	Chrysotile 5%	Carbonates Quartz Binder/Filler	95%
		LAYER# 2 Mastic, Yellow	No		Gypsum Binder/Filler	100%
		LAYER# 3 Vinyl Sheet Flooring, Beige	Yes	Chrysotile 15%	Carbonates Gypsum Binder/Filler	85%
		LAYER# 4 Mastic, Brown	Yes	Chrysotile 2%	Cellulose Fiber Gypsum Binder/Filler	1% 97%

# EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044  
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report  
**0009557**

## Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	NINYO & MOORE	Job# / P.O. #:	301218001
Address:	3155 E. PATRICK LANE, STE 12 LAS VEGAS NV 89120	Date Received:	03/12/2003
Collected:	03/06/2003	Date Analyzed:	03/12/2003
Project Name/	TONOPAH/PINK MOTEL	Date Reported:	03/12/2003
Address:	201 MAIN STREET	EPA Method:	EPA 600/M4-82-020
		Submitted By:	ROBERT TROISI
		Collected By:	Customer

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0009557-029 B-029	BLDG 3 UNIT 17 RESTRM	LAYER# 1 Vinyl Sheet Flooring, Brown	No		Cellulose Fiber Fibrous Glass  Gypsum Quartz Binder/Filler	20% 2%  78%
		LAYER# 2 Mastic, Yellow Note: Difficult to separate adjacent layers	No		Cellulose Fiber  Gypsum Binder/Filler	2% 98%
		LAYER# 3 Leveling Compound, White	Yes	Chrysotile 3%	Carbonates Mica Quartz Binder/Filler	97%
0009557-030 B-030	BLDG 3 UNIT 12 BEDRM	Texture Ceiling Tile, White/ Yellow	No		Cellulose Fiber  Binder/Filler	95% 5%
0009557-031 B-031	BLDG 3 UNIT 12 RESTRM	LAYER# 1 Vinyl Sheet Flooring, Brown	No		Cellulose Fiber Fibrous Glass  Gypsum Quartz Binder/Filler	15% 2%  83%
		LAYER# 2 Mastic, Brown	No		Cellulose Fiber  Gypsum Binder/Filler	2% 98%
		LAYER# 3 Vinyl Sheet Flooring, Gray, Black	Yes	Chrysotile 15%	Gypsum Carbonates Binder/Filler	85%
		LAYER# 4 Mastic, Brown	Yes	Chrysotile 2%	Cellulose Fiber  Gypsum Quartz Binder/Filler	<1% 97%

# EMC LABS, INC.

Laboratory Report  
0009557

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044  
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

## Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	NINYO & MOORE	Job# / P.O. #:	301218001
Address:	3155 E. PATRICK LANE, STE 12	Date Received:	03/12/2003
	LAS VEGAS NV 89120	Date Analyzed:	03/12/2003
Collected:	03/06/2003	Date Reported:	03/12/2003
Project Name/	TONOPAH/PINK MOTEL	EPA Method:	EPA 600/M4-82-020
Address:	201 MAIN STREET	Submitted By:	ROBERT TROISI
		Collected By:	Customer

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0009557-032 B-032	BLDG 3 UNIT 23 RESTRM	LAYER# 1 Vinyl Sheet Flooring, White/ Lt. Green	Yes	Chrysotile 15%	Gypsum Binder/Filler 85%
		LAYER# 2 Mastic, Brown	Yes	Chrysotile 2%	Gypsum Binder/Filler 98%
		LAYER# 3 Felt, Black	No		Cellulose Fiber Carbonates Binder/Filler 30% 70%
0009557-033 B-033	BLDG 3 UNIT 23 BEDRM	Ceiling Tile, White/ Yellow	No		Cellulose Fiber 95%
					Binder/Filler 5%
0009557-034 B-034	BLDG 4 UNIT 35 BEDRM	28x16 Ceiling Tile, White/ Yellow	No		Cellulose Fiber 95%
					Binder/Filler 5%
0009557-035 B-035	BLDG 4 UNIT 35 RESTRM	LAYER# 1 Drywall, White, Brown	No		Cellulose Fiber 10%
					Gypsum Carbonates Mica Quartz Binder/Filler 90%
		LAYER# 2 Joint Compound, White	Yes	Chrysotile 2%	Carbonates Mica Quartz Binder/Filler 98%
		LAYER# 3 Texture, White	Yes	Chrysotile 2%	Carbonates Mica Quartz Binder/Filler 98%

# EMC LABS, INC.

Laboratory Report  
0009557

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044  
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

## Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	NINYO & MOORE	Job# / P.O. #:	301218001
Address:	3155 E. PATRICK LANE, STE 12 LAS VEGAS NV 89120	Date Received:	03/12/2003
Collected:	03/06/2003	Date Analyzed:	03/12/2003
Project Name/	TONOPAH/PINK MOTEL	Date Reported:	03/12/2003
Address:	201 MAIN STREET	EPA Method:	EPA 600/M4-82-020
		Submitted By:	ROBERT TROISI
		Collected By:	Customer

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0009557-036 B-036	BLDG 4 UNIT 35 RESTRM CEILNG	LAYER# 1 12x12 Vinyl Floor Tile, Gray	No		
		LAYER# 2 Mastic, Yellow	No	Carbonates Quartz Binder/Filler	100%
		LAYER# 3 Backing, Brown	No	Gypsum Cellulose Fiber Fibrous Glass Gypsum Quartz Binder/Filler	65% 5% 30%
0009557-037 B-037	BLDG 4 UNIT 38 RESTRM	LAYER# 1 Drywall, White, Brown	No	Cellulose Fiber Fibrous Glass	10% 2%
		LAYER# 2 Joint Compound, White	No	Gypsum Carbonates Mica Quartz Binder/Filler	88%
		LAYER# 3 Texture, White	No	Carbonates Quartz Binder/Filler	100%
0009557-038 B-038	BLDG 4 UNIT 38 RESTRM	LAYER# 1 12x12 Vinyl Floor Tile, Gray	No	Carbonates Binder/Filler	100%
		LAYER# 2 Mastic, Yellow	No	Gypsum Carbonates Quartz Binder/Filler	100%

# EMC LABS, INC.

Laboratory Report

0009557

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044  
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

## Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	NINYO & MOORE	Job# / P.O. #:	301218001
Address:	3155 E. PATRICK LANE, STE 12 LAS VEGAS NV 89120	Date Received:	03/12/2003
Collected:	03/06/2003	Date Analyzed:	03/12/2003
Project Name/	TONOPAH/PINK MOTEL	Date Reported:	03/12/2003
Address:	201 MAIN STREET	EPA Method:	EPA 600/M4-82-020
		Submitted By:	ROBERT TROISI
		Collected By:	Customer

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0009557-039 B-039	BLDG 4 UNIT 39 BEDRM CEILING	12x12 Textured Ceiling Tile, White/ Yellow	No		Cellulose Fiber Binder/Filler	95% 5%
0009557-040 B-040	BLDG 4 UNIT 39 RESTRM CEILING	LAYER# 1 Joint Compound, White	No		Carbonates Mica Quartz Binder/Filler	100%
		LAYER# 2 Texture, White	No		Carbonates Mica Quartz Binder/Filler	100%
0009557-041 B-041	BLDG 2 UNIT 10 BEDRM CEILING	LAYER# 1 Drywall, White, Brown	No		Cellulose Fiber Gypsum Carbonates Mica Quartz Binder/Filler	10% 90%
		LAYER# 2 Joint Compound, White	Yes	Chrysotile 3%	Carbonates Mica Quartz Binder/Filler	97%
		LAYER# 3 Texture/Paint, White	Yes	Chrysotile 2%	Cellulose Fiber Carbonates Mica Quartz Binder/Filler	<1% 97%

# EMC LABS, INC.

Laboratory Report  
0009557

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044  
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

## Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	NINYO & MOORE	Job# / P.O. #:	301218001
Address:	3155 E. PATRICK LANE, STE 12 LAS VEGAS NV 89120	Date Received:	03/12/2003
Collected:	03/06/2003	Date Analyzed:	03/12/2003
Project Name/	TONOPAH/PINK MOTEL	Date Reported:	03/12/2003
Address:	201 MAIN STREET	EPA Method:	EPA 600/M4-82-020
		Submitted By:	ROBERT TROISI
		Collected By:	Customer

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0009557-042 B-042	BLDG 2 ROOF	LAYER# 1 Roof Material, White, Black	Yes	Chrysotile 30%	Cellulose Fiber Fibrous Glass Carbonates Binder/Filler 5% 3%
		LAYER# 2 Roof Mastic, Black	No		Cellulose Fiber Carbonates Binder/Filler 40% 60%
		LAYER# 3 Roof Mastic, Black	No		Cellulose Fiber Carbonates Binder/Filler 40% 60%
0009557-043 B-043	BLDG 2 ROOF	Roof Mastic, Gray, Black	No		Cellulose Fiber Carbonates Binder/Filler 10% 90%
0009557-044 B-044	BLDG 2 ROOF	Vent Pipe, Beige, White	Yes	Chrysotile 20% Crocidolite 2%	Carbonates Gypsum Quartz Binder/Filler 78%
0009557-045 B-045	BLDG 2 AWNING ROOF	Asphalt Shingle, White, Black	No		Cellulose Fiber Carbonates Quartz Binder/Filler 25% 75%
0009557-046 B-046	POOL STEPS	Pool Wall Material, White/ Beige	No		Carbonates Quartz Binder/Filler 100%
0009557-047 B-047	POOL CONCRETE EDGING	Pool Concrete Edging, White/ Tan	No		Quartz Carbonates Gypsum Mica Binder/Filler 100%

# EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044  
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report  
**0009557**

## Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	NINYO & MOORE	Job# / P.O. #:	301218001
Address:	3155 E. PATRICK LANE, STE 12	Date Received:	03/12/2003
	LAS VEGAS NV 89120	Date Analyzed:	03/12/2003
Collected:	03/06/2003	Date Reported:	03/12/2003
Project Name/	TONOPAH/PINK MOTEL	EPA Method:	EPA 600/M4-82-020
Address:	201 MAIN STREET	Submitted By:	ROBERT TROISI
		Collected By:	Customer

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0009557-048 B-048	POOL HOUSE ROOF	LAYER# 1 Asphalt Shingle, White, Black	No		Cellulose Fiber Carbonates Quartz Binder/Filler	25% 75%
		LAYER# 2 Felt, Black	No		Cellulose Fiber Carbonates Binder/Filler	35% 65%
0009557-049 B-049	BLDG 5 MECH RM ROOF	LAYER# 1 Rolled Roofing, Black/Orange/Beige	No		Fibrous Glass Carbonates Quartz Binder/Filler	20% 80%
		LAYER# 2 Rolled Roofing, Silver/Black	No		Carbonates Binder/Filler	100%
		LAYER# 3 Rolled Roofing, Black	Yes	Chrysotile 5%	Cellulose Fiber Carbonates Binder/Filler	30% 65%
0009557-050 B-050	BLDG 5 UNIT 3 BEDRM WALL	LAYER# 1 Drywall, White, Brown	No		Cellulose Fiber Quartz Mica Gypsum Carbonates	10% 90%
		LAYER# 2 Joint Compound, White	No		Quartz Mica Carbonates	100%

# EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044  
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report  
**0009557**

## Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	NINYO & MOORE	Job# / P.O. #:	301218001
Address:	3155 E. PATRICK LANE, STE 12 LAS VEGAS NV 89120	Date Received:	03/12/2003
Collected:	03/06/2003	Date Analyzed:	03/12/2003
Project Name/	TONOPAH/PINK MOTEL	Date Reported:	03/12/2003
Address:	201 MAIN STREET	EPA Method:	EPA 600/M4-82-020
		Submitted By:	ROBERT TROISI
		Collected By:	Customer

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0009557-051 B-051	BLDG 5 UNIT 3 UTILITY RM FL	LAYER# 1 12x12 VFT, White/Gray	No		Quartz Carbonates Binder/Filler	100%
		LAYER# 2 Mastic, Yellow	No		Carbonates Binder/Filler	
0009557-052 B-052	BLDG 5 UNIT 3 RESTRM SHOWER WALL	LAYER# 1 Ceramic Tile, White/Red	No		Quartz Gypsum Binder/Filler	100%
		LAYER# 2 Mortar, Gray	Yes	Chrysotile <1%	Quartz Mica Carbonates Binder/Filler	
0009557-053 B-053	BLDG 5 UNIT 5 BEDRM WALL	LAYER# 1 Drywall, White, Brown	No		Cellulose Fiber	10%
		LAYER# 2 Joint Compound, White	Yes	Chrysotile 3%	Quartz Mica Gypsum Carbonates	
					Binder/Filler	97%

# EMC LABS, INC.

Laboratory Report

0009557

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044  
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

## Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	NINYO & MOORE	Job# / P.O. #:	301218001
Address:	3155 E. PATRICK LANE, STE 12 LAS VEGAS NV 89120	Date Received:	03/12/2003
Collected:	03/06/2003	Date Analyzed:	03/12/2003
Project Name/	TONOPAH/PINK MOTEL	Date Reported:	03/12/2003
Address:	201 MAIN STREET	EPA Method:	EPA 600/M4-82-020
		Submitted By:	ROBERT TROISI
		Collected By:	Customer

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0009557-054 B-054	BLDG 5 UNIT 5 UTILITY RM FL	LAYER# 1 12x12 VFT, White/Gray	No		Quartz Carbonates Binder/Filler	100%
		LAYER# 2 Mastic, Yellow	No		Cellulose Fiber Carbonates Binder/Filler	2% 98%
0009557-055 B-055	BLDG 5 UNIT 5 BEDRM CEILING	LAYER# 1 Drywall, White, Brown	No		Cellulose Fiber	10%
		LAYER# 2 Joint Compound, White	Yes	Chrysotile 3%	Quartz Mica Gypsum Carbonates	90%
0009557-056 B-056	BLDG 5 UNIT 7 RESTRM WALL	LAYER# 1 Drywall, White, Brown	No		Cellulose Fiber	10%
		LAYER# 2 Joint Compound, White	Yes	Chrysotile 3%	Quartz Mica Gypsum Carbonates	90%
					Quartz Mica Carbonates	97%

# EMC LABS, INC.

Laboratory Report

**0009557**

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044  
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

## Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	NINYO & MOORE	Job# / P.O. #:	301218001
Address:	3155 E. PATRICK LANE, STE 12	Date Received:	03/12/2003
	LAS VEGAS NV 89120	Date Analyzed:	03/12/2003
Collected:	03/06/2003	Date Reported:	03/12/2003
Project Name/	TONOPAH/PINK MOTEL	EPA Method:	EPA 600/M4-82-020
Address:	201 MAIN STREET	Submitted By:	ROBERT TROISI
		Collected By:	Customer

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0009557-057 B-057	BLDG 5 UNIT 7 RESTRM FL	LAYER# 1 12x12 VFT, White/Gray	No		Quartz Carbonates Binder/Filler 100%
		LAYER# 2 Mastic, Yellow	No		Cellulose Fiber 1% Quartz Carbonates Binder/Filler 99%
0009557-058 B-058	BLDG 5 UNIT 9 BEDRM WALL	LAYER# 1 Drywall, White, Brown	No		Cellulose Fiber 10%
		LAYER# 2 Joint Compound, White	Yes	Chrysotile 3%	Quartz Mica Gypsum Carbonates 90%
					Quartz Mica Carbonates 97%
0009557-059 B-059	BLDG 5 ROOF	LAYER# 1 Rolled Roofing, Black/Orange/Beige	No		Fibrous Glass 15%
		LAYER# 2 Rolled Roofing, Black/Gray	Yes	Chrysotile 15%	Quartz Carbonates Binder/Filler 85%
		LAYER# 3 Rolled Roofing, Black	No		Carbonates Binder/Filler 85%
					Cellulose Fiber 60%
					Carbonates Binder/Filler 40%
0009557-060 B-060	BLDG 5 ROOF	Roofing Mastic, Black	Yes	Chrysotile 10%	Carbonates Binder/Filler 90%

# EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044  
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report  
**0009557**

## Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	NINYO & MOORE	Job# / P.O. #:	301218001
Address:	3155 E. PATRICK LANE, STE 12 LAS VEGAS NV 89120	Date Received:	03/12/2003
Collected:	03/06/2003	Date Analyzed:	03/12/2003
Project Name/	TONOPAH/PINK MOTEL	Date Reported:	03/12/2003
Address:	201 MAIN STREET	EPA Method:	EPA 600/M4-82-020
		Submitted By:	ROBERT TROISI
		Collected By:	Customer

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0009557-061 B-061	BLDG 4 UNIT 48 RESTRM	LAYER# 1 Drywall, White, Brown	No		Cellulose Fiber Quartz Mica Gypsum Carbonates	10% 90%
		LAYER# 2 Joint Compound, White	No		Quartz Carbonates Binder/Filler	100%
0009557-062 B-062	BLDG 4 UNIT 48 RESTRM	LAYER# 1 12x12 Vinyl Floor Tile, White/ Gray	No		Carbonates Binder/Filler	100%
		LAYER# 2 Mastic, Tan	No		Quartz Carbonates Binder/Filler	100%
0009557-063 B-063	BLDG 4 UNIT 49 BEDRM	28x16 Ceiling Tile, White/ Tan	No		Cellulose Fiber Carbonates Binder/Filler	90% 10%
0009557-064 B-064	BLDG 4 UNIT 49 BEDRM	LAYER# 1 Drywall, Brown/ Off White	No		Cellulose Fiber Quartz Mica Gypsum Carbonates	10% 90%
		LAYER# 2 Joint Compound, White	No		Quartz Mica Carbonates	100%

# EMC LABS, INC.

Laboratory Report

0009557

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044  
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

## Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	NINYO & MOORE	Job# / P.O. #:	301218001
Address:	3155 E. PATRICK LANE, STE 12	Date Received:	03/12/2003
	LAS VEGAS NV 89120	Date Analyzed:	03/12/2003
Collected:	03/06/2003	Date Reported:	03/12/2003
Project Name/	TONOPAH/PINK MOTEL	EPA Method:	EPA 600/M4-82-020
Address:	201 MAIN STREET	Submitted By:	ROBERT TROISI
		Collected By:	Customer

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0009557-065 B-065	BLDG 4 UNIT 50 RESTRM	LAYER# 1 Drywall, Brown/ Off White	No		Cellulose Fiber Quartz Mica Gypsum Carbonates	10% 90%
		LAYER# 2 Joint Compound, White	No		Quartz Mica Carbonates	100%
0009557-066 B-066	BLDG 4 MGRS APT ROOF	LAYER# 1 Asphalt Shingle Roof, Beige, Black	No		Fibrous Glass Quartz Carbonates Binder/Filler	15% 85%
		LAYER# 2 Asphalt Shingle Roof/ Felt, Black	No		Cellulose Fiber Carbonates Binder/Filler	45% 55%
0009557-067 B-067	BLDG 4 MGRS APT ROOF	Roofing Mastic, Black	No		Cellulose Fiber Carbonates Binder/Filler	15% 85%
0009557-068 B-068	BLDG 4 MGRS APT ENTRANCE	LAYER# 1 Drywall, Brown/ Off White	No		Cellulose Fiber Quartz Mica Gypsum Carbonates	10% 90%
		LAYER# 2 Joint Compound, White	Yes	Chrysotile 3%	Quartz Mica Carbonates Binder/Filler	97%

# EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044  
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726


Laboratory Report  
**0009557**

## Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	NINYO & MOORE	Job# / P.O. #:	301218001
Address:	3155 E. PATRICK LANE, STE 12 LAS VEGAS NV 89120	Date Received:	03/12/2003
Collected:	03/06/2003	Date Analyzed:	03/12/2003
Project Name/	TONOPAH/PINK MOTEL	Date Reported:	03/12/2003
Address:	201 MAIN STREET	EPA Method:	EPA 600/M4-82-020
		Submitted By:	ROBERT TROISI
		Collected By:	Customer

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0009557-069 B-069	BLDG 4 MGRS APT LIVING RM	Ceiling Tile, White/ Tan/Grooved	No		Cellulose Fiber	90%
					Carbonates Binder/Filler	10%
0009557-070 B-070	BLDG 4 MGRS APT FAMILY RM	LAYER# 1 Vinyl Sheet Flooring, Tan	Yes	Chrysotile 20%	Cellulose Fiber	3%
		LAYER# 2 Mastic, Tan	Yes	Chrysotile 3%	Gypsum Carbonates Binder/Filler	77%
					Cellulose Fiber	2%
					Carbonates Binder/Filler	95%

  
Analyst - Brad Yanbin Ai

  
Signatory - Lab Director - Kurt Kettler

Distinctly stratified, easily separable layers of samples are analyzed as subsamples of the whole and are reported separately for each discernable layer. All analyses are derived from calibrated visual estimate and measured in weight percent unless otherwise noted. The report applies to the standards or procedures identified and to the sample(s) tested. The test results are not necessarily indicative or representative of the qualities of the lot from which the sample was taken or of apparently identical or similar products, nor do they represent an ongoing quality assurance program unless so noted. These reports are for the exclusive use of the addressed client and that they will not be reproduced wholly or in part for advertising or other purposes over our signature or in connection with our name without special written permission. The report shall not be reproduced except in full, without written approval by our laboratory. The samples not destroyed in testing are retained a maximum of thirty days. The laboratory measurement of uncertainty for the test method is approximately <1% by weight. Of Standards and Technology, Voluntary Laboratory Accreditation Program for selected test method for asbestos. The accreditation or any report generated by this laboratory in no way constitutes or implies product certification, approval, or endorsement by the National Institute of Standards and Technology. The report must not be used by any entity to claim product endorsement by NVLAP or any agency of the U.S. Government. Polarized Light Microscopy may not be consistently reliable in detecting asbestos in floor coverings and similar non-fibrous organically bound materials.

Page \_\_\_\_ of \_\_\_\_

**CHAIN OF CUSTODY**

EMC Laboratories  
 9830 S. 51<sup>ST</sup> St., Ste B-109  
 Phoenix, AZ 85044  
 (800) 362-3373 Fax (480) 893-1726

LAB#:

9557  
Rush

TAT:

Rec'd: MAR 12 A.M.

COMPANY NAME: **NINYO & MOORE**3155 E. PATRICK LANE, STE 12  
LAS VEGAS, NV 89120

BILL TO:

(If different Location)

CONTACT: ROGER GREEN

Phone/Fax: (702) 433-0330 / (702) 433-0707

Email: rgreen@ninyoandmoore.com

Now Accepting: **VISA – MASTERCARD**FAXED E-MAILED  
3/12/03Price Quoted: \$ 12<sup>ea</sup> / Sample \$ \_\_\_\_\_ / Layers**COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)**1. TURNAROUND TIME: [4hr rush] [8hr rush] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]

\*\*\*Prior confirmation of turnaround time is required

\*\*\*Additional charges for rush analysis (please call marketing department for pricing details)

\*\*\*Laboratory analysis may be subject to delay if credit terms are not met

2. TYPE OF ANALYSIS: [Bulk-PLM] [Air-PCM] [Lead] [Point Count]3. DISPOSAL INSTRUCTIONS: [Dispose of samples at EMC] / [Return samples to me at my expense]

(If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

4. Project Name: Ionaph /Pink Motel - 201 Main StP.O. Number: \_\_\_\_\_ Project Number: 301218001

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No	AIR SAMPLE INFO / COMMENTS ON	OFF	FLOW RATE
1	B-001	3/8		Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			

SPECIAL INSTRUCTIONS: \_\_\_\_\_

Sample Collector: (Print)

(Signature)

Inlinquished by:	Date/Time:	Received by:	Date/Time:
<u>Diana Fedurice</u>		<u>Diana Fedurice</u>	<u>3/12/03</u>
Inlinquished by:	Date/Time:	Received by:	Date/Time:
<u>Diana Fedurice</u>	<u>3/12/03</u>	<u>JL</u>	<u>3-12-03</u>
Inlinquished by:	Date/Time:	Received by:	Date/Time:

\* In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

\* 2 extra charges for chasserie leases.

# ASBESTOS BULK SAMPLE DATA SHEET

Ninyo & Moore  
 3155 East Patrick Lane, Suite 12  
 Las Vegas, Nevada 89120  
 Tel: (702) 433-0330  
 Fax: (702) 433-0707

Project Name: TONOPAH / PINK MOTEL  
 Project No.: 30/2/8001  
 Project Manager: Robert Trois.  
 APN:  
 Site Address: 201 MAIN STREET

## CHAIN OF CUSTODY INFORMATION:

Relinquished By: (sign/print)	Company	Date	Time(24 hr)	Received By: (sign/print)	Laboratory		
LabID	Sample ID	Building Number	Sample Location	Sample Description	Quantity (SF/LF/EA)	Friable (Y/N)	Condition
<i>Robert Trois, Robert Trois.</i>	Ninyo&Moore	3/11/03	1535	<i>Alvaro-Tecnologia DIANA FEDERICO</i>	E. M. C.		
<i>Diana-Tecnologia DIANA FEDERICO</i>	E. M. C.			<i>Alvaro-Tecnologia DIANA FEDERICO</i>	E. M. C.		
B-001	#1	BLDG #1 UNIT 2 WALL SYSTEM	WALL TEXTURE W/ WALL PLASTER + BOARD	WALL TEXTURE W/ WALL PLASTER + BOARD	Y	Y	G
B-002	#1	BLDG. #1 WALL SYSTEM	JNT COMPOUND AND WALL PLASTER	JNT COMPOUND AND WALL PLASTER	N	N	
B-003	#1	N.E. CORNER BLDG. #1 EXTERIOR WALL	Exterior stucco OVER CONCRETE BRICKS	Exterior stucco OVER CONCRETE BRICKS	N	N	
B-004	#1	BLDG. #1 UNIT 3 BEDROOM	9"X9" REDBROWN VINYL FLOOR TILE	9"X9" REDBROWN VINYL FLOOR TILE	2,34	N	
B-005	#1	BLDG. #1 UNIT 1 BEDROOM	9"X9" GRAY VINYL FLOOR TILE	9"X9" GRAY VINYL FLOOR TILE	1,2	N	
B-006	#1	BLDG. #1 UNIT 1 BATHROOM	TAN VINYL SHEET FLOORING	TAN VINYL SHEET FLOORING	14	Y	
B-007	#1	BLDG. #1 UNIT 3 BATHROOM	BROWN VINYL SHEET FLOORING	BROWN VINYL SHEET FLOORING	2,3	Y	
B-008	#1	BLDG. #1 UNIT 4 WALL SYSTEM	WALL TEXTURE W/ WALL PLASTER AND BOARD	WALL TEXTURE W/ WALL PLASTER AND BOARD	Y	Y	
B-009	#1	BLDG. #1 UNIT 4 SHOWER STALL	SHOWER WALL VENEER W/ MASTIC	SHOWER WALL VENEER W/ MASTIC	N	N	
B-010	#1	BLDG. #1, UNIT 3 BATHROOM	CERAMIC TILE W/ MASTIC AROUND TUB	CERAMIC TILE W/ MASTIC AROUND TUB	N	N	
B-011	#1	SL. CORNER BLDG. #1 EXTERIOR WALL	EXTERIOR STUCCO OVER CONCRETE BRICKS	EXTERIOR STUCCO OVER CONCRETE BRICKS	N	N	
B-012	#1	BLDG. #1 UNIT 3 BATHROOM	JNT COMPOUND AND WALL PLASTER	JNT COMPOUND AND WALL PLASTER	N	N	V

# ASBESTOS BULK SAMPLE DATA SHEET

Sheet - 5f  
95'

<b>Ninyo &amp; Moore</b>	Project Name: <b>TORO PAH / PINK MOTEL</b>	Sampled By: <b>R. TROIS /</b>	Laboratory: <b>Eme</b>
3155 East Patrick Lane, Suite 12	Project No.: <b>301218 AD/</b>	Sampled By:	
Las Vegas, Nevada 89120	Project Manager: <b>Robert M. Trois /</b>	Sampled By:	
APN: <b></b>	Date Sampled: <b>3-6-03</b>	Date Sampled:	
Site Address: <b>201 Main Street</b>	Tel: <b>3-6-03</b>	Fax: <b>3-6-03</b>	

## CHAIN OF CUSTODY INFORMATION:

Relinquished By (signature)		Company	Date	Time(D/24 hr)	Received By (signature)	Laboratory	
<i>Robert M. Trois,</i>	<i>Ninyo &amp; Moore</i>	<i>3/11/03</i>	<i>1535</i>		<i>Diana Federico</i>	<i>E. M. C.</i>	
<i>Diana Federico</i>	<i>E. M. C.</i>				<i>Ari Yan B/N</i>	<i>Eme</i>	
LabID	Sample ID	Building Number	Sample Location	Sample Description	Quantity (SF/LF/EA)	Friable (Y/N)	Condition
B-013	#2	BLDG. #2 UNIT 7 WALL STEM	WALL TEXTURE w/ WALL PLASTER AND BOARD		Y	Y	G
B-014	#2	BLDG. #2 UNIT 8 CEILING	DRY WALL AND CEILING TEXTURE		Y	Y	G
B-015	#2	BLDG. #2 UNIT 10 BATHROOM	CERAMIC TILE AND MORTAR		N	Y	G
B-016	#2	BLDG. #2 UNIT 9 BEDROOM	DRY WALL AND JOINT COMPOUND		N	Y	G
B-017	#2	BLDG. #2 UNIT 10 BEDROOM	WALL TEXTURE OVER WALL PLASTER		Y	Y	G
B-018	#3	BLDG. #3 OFFICE KITCHEN AREA	BROWN/TAN VINYL SHEET FLOORING		Y	Y	G
B-019	#3	BLDG. #3 UNIT 19 BEDROOM	DRY WALL, JOINT COMPOUND & TEXTURE SEPARATION WALLS ONLY		N	Y	D
B-020	#3	BLDG. #3 UNIT 19 BEDROOM	CEILING TILE SOLID FRONT		Y	Y	D
B-021	#3	BLDG. #3 UNIT 28 BEDROOM	DRYWALL, JOINT COMPOUND		N	Y	D
B-022	#3	BLDG. #3 UNIT 28 BEDROOM	CEILING TILE		Y	Y	D
B-023	#3	BLDG. #3 UNIT 20 BEDROOM	TAN/WHITE VINYL SHEET FLOORING		Y	Y	G
B-024	#3	BLDG. #3 UNIT 20 BEDROOM	CEILING TILE WITH HOLES		Y	Y	D

**ASBESTOS BULK SAMPLE DATA SHEET**

Ninyo & Moore  
 Project No.: 301/2/8001  
 Project Manager: Robert Troisi  
 APN:  
 Site Address: 201 Main Street  
 Tel: (702) 433-0330  
 Fax: (702) 433-0707

Project Name: TANOPATH/PINK MOTHER  
 Sampled By:  
 Sampled By:  
 Sampled By:  
 Date Sampled: 3-07-03  
 Tel:  
 Fax:

**CHAIN OF CUSTODY INFORMATION:**

Relinquished By (Signature)		Company	Date	Time (24 hr.)	Received By (Signature)	Laboratory	
LabID	Sample ID	Building Number	Sample Location	Sample Description	Quantity (SF/LF/EA)	Friable (Y/N)	Condition
B-025	#3	BDS. #3 OFFICE	MAIN OFFICE	9"X9" Brown vinyl floor tile & mastic		Y	G
B-026	#3	BDS. #3 UNIT 18	UNIT 18	12"X12" White/gray VINYL FLOOR TILE		N	G
B-027	#3	BDS. #3 UNIT 19	UNIT 19	White/Gray VINYL FLOOR TILE		N	G
B-028	#3	BDS. #3 UNIT 27	UNIT 27	White/Gold VINYL FLOOR TILE OVER TAN GOLD VINYL STREET FLOORING		Y	G
B-029	#3	BDS. #3 UNIT 17	UNIT 17	Brown square vinyl street flooring		Y	G
B-030	#3	BDS. #3 UNIT 12	UNIT 12	White textured ceiling tile		Y	D
B-031	#3	BDS. #3 UNIT 12	UNIT 12	Brown VINYL STREET FLOORING OVER PALE GREEN VINYL STREET FLOORING		Y	G
B-032	#3	BDS. #3 RESTROOM	RESTROOM	White speckle VINYL STREET FLOORING		Y	G
B-033	#3	BDS. #3 BED ROOM	BED ROOM	White ceiling tile with holes		Y	D
B-034	#4	BDS. #4 UNIT 35	UNIT 35	28"X16" white ceiling tile		Y	D
B-035	#4	BDS. #4 UNIT 35	UNIT 35	drywall, joint compound		N	D
B-036	#4	BDS. #4 RESTROOM	RESTROOM	12"X12" gray vinyl floor tile		N	G

## ASBESTOS BULK SAMPLE DATA SHEET

Project Name: TONY PAUL / DICK MISTER		Sampled By: R. THOMAS		Laboratory: EMC	
Project No.: 30121800 /		Sampled By:			
Project Manager: Robert Trosiisi		Sampled By:			
APN:		Date Sampled: 3-07-03		Tel: 3-08-03	
Site Address: 201 MAIN STREET		Fax: 3-08-03		<b>RUSTY</b>	
CHAIN OF CUSTODY INFORMATION:		Received By: (signature)		Laboratory	
<i>Robert Trosiisi</i>		<i>Al Yanbu</i>		E. M. C.	
<i>Owner/Federicoiana Federico</i>		<i>Al Yanbu</i>		E. M. C.	
Relinquished By: (signature)	Company	Date	Time (24 hr)	E. M. C.	
<i>Robert Trosiisi</i>	Nyno&Moore	3/11/03	1535	Owner/Technics/DIANA FEDERICO	
LabID	Sample ID	Building Number	Sample Location	Sample Description	Quantity (SF/LF/EA) (Y/N)
B-037	#4	BLDG. #4 UNIT 38 Restroom ceiling	drywall, joint compound	12" x 12" vinyl floor tile	N D
B-038	#4	BLDG. #4 UNIT 38 RESTROOM	drywall, joint compound	12" x 12" white textured ceiling tile	N G
B-039	#4	BLDG. #4 UNIT 39 BEDROOM	joint compound + texture	12" x 12" white textured ceiling tile	X D
B-040	#4	BLDG. #4 RESTROOM CEILING	dry wall & texture	12" x 12" white textured ceiling tile	X D
B-041	#2	BLDG. #2 BEDROOM CEILING	dry wall & texture	12" x 12" white textured ceiling tile	X D
B-042	#2	BLDG. #2 ROOF	roll-on roof	12" x 12" white textured ceiling tile	X D
B-043	#2	BLDG. #2 ROOF	Roofing mastic	12" x 12" white textured ceiling tile	N G
B-044	#2	BLDG #2 ROOF	VENT PIPE	12" x 12" white textured ceiling tile	N
B-045	#2	BLDG #2 AWNING ROOF	Asphalt shingle	12" x 12" white textured ceiling tile	N
B-046	Pool	Pool steps	Pool wall material	12" x 12" white textured ceiling tile	N
B-047	Pool	Pool concrete edging	Pool edge near steps	12" x 12" white textured ceiling tile	N
B-048	Pool	Pool house roof	Asphalt shingle	12" x 12" white textured ceiling tile	N

# ASBESTOS BULK SAMPLE DATA SHEET

957

<b>Ninyo &amp; Moore</b>	Project Name: TONOPAH / PINK MOUNTAIN	Sampled By: R. TRONI	Laboratory: EMC
Project No.: 301218001	Sampled By:		
Project Manager: Robert Troni's	Sampled By:		
APN:	Date Sampled: 3/08/03	Tel:	RUSH
Site Address: 201 MAIN STREET	Fax:		

## CHAIN OF CUSTODY INFORMATION:

Relinquished By (signature)	Received By (signature)	Comments (24hr)	Laboratory
<i>Robert Troni, Robert Troni's Diana Federico</i>	<i>Diana Federico</i>		E.M.C.
<i>E. M. C.</i>	<i>Alyanis</i>		EMC
LabID	Sample ID	Company	Date
		Sample Location	Time(24hr)
B-049	#5	BLDG #5 MECHANICAL ROOM ROOF	ROLL - ON ROOF
B-050	#5	BLDG #5 UNIT 3 BEDROOM WALL	DEY WATE, joint compound
B-051	#5	BLDG #5 UNIT 3 UTILITY ROOM FLOOR	12" x 12" White/gray vinyl floor tile
B-052	#5	BLDG #5 UNIT 3 RESTROOM SHOWER WALL	CERAMIC TILE
B-053	#5	BLDG #5 UNIT 5 BEDROOM WALL	DRYWALL, joint compound
B-054	#5	BLDG #5 UNIT 5 UTILITY ROOM FLOOR	12" x 12" white/gray floor tile
B-055	#5	BLDG #5 BEDROOM CEILING	DEY WATE, joint compound
B-056	#5	BLDG #5 RESTROOM WALL	DRYWALL, joint compound
B-057	#5	BLDG #5 RESTROOM FLOOR	12" x 12" White/gray floor tile
B-058	#5	BLDG #5 BEDROOM WALL	DEY WATE, joint compound
B-059	#5	BLDG #5 ROOF	ROLL - ON ROOF
B-060	#5	BLDG #5 ROOF	Roofing mastic

# ASBESTOS BULK SAMPLE DATA SHEET

Ninyo & Moore 3155 East Patrick Lane, Suite 12 Las Vegas, Nevada 89120 Tel: (702) 433-0330 Fax: (702) 433-0707	Project Name: TAVORAH / PINK MOTEL Project No.: 301218001 Project Manager: Robert M. Tosis/ APN: Site Address: 201 MAIN STREET	Sampled By: R. TRAVIS/ Sampled By: Sampled By: Date Sampled: 03/08/03	Laboratory: EMC
<b>CHAIN OF CUSTODY INFORMATION:</b>			
Relinquished By (signature) <i>Robert M. Tosis</i> , Robert M. Tosis, Owner - Indiana DIANA FEDERICO			
LabID	Sample ID	Company	Date
B-061	#4	Ninoy & Moore	3/11/03
B-062	#4	E. M. C.	
B-063	#4	Building #4 Unit 48 Restroom	day wear and joint compound
B-064	#4	Bldg. #4 Unit 48 Restroom	12" x 12" white/gray vinyl floor tile
B-065	#4	Bldg. #4 Unit 49 Restroom	28" x 16" white ceiling tile
B-066	#4	Bldg. #4 Unit 49 Restroom	drywall and joint compound
B-067	#4	Bldg. #4 Mgrs Apt. Roof	asphalt shingle roof
B-068	#4	Bldg. #4 mrgs Apt. ENTRANCE	roofing mastic drywall + joint compound
B-069	#4	Bldg. #4 mrgs Apt. Living room	white grooved ceiling tile
B-070	#4	Bldg. #4 mrgs Apt. Family room	large sheet flooring



9830 South 51<sup>st</sup> Street, Suite B-109 / PHOENIX, ARIZONA 85044 / 480-940-5294 or 800-362-3373 / FAX 480-893-1726  
emclab@emclabs.com

**LEAD (Pb) IN PAINT CHIP SAMPLES**  
EMC SOP METHOD #L01/1      EPA SW-846 METHOD 7420

EMC LAB #: L23335			DATE RECEIVED: 03/13/03		
CLIENT: Ninyo & Moore			REPORT DATE: 03/13/03		
			DATE OF ANALYSIS: 03/13/03		
CLIENT ADDRESS: 3155 E. Patrick Lane., Ste 12 Las Vegas, NV 89120			P.O. NO.:		
PROJECT NAME: Tonopah/Pink Motel 201 Main Street			PROJECT NO.: 301218001		
EMC # L23335-	SAMPLE DATE /03	CLIENT SAMPLE #	DESCRIPTION	REPORTING LIMIT IN PPM	Pb IN PPM
1	03/12	PC-001	Bldg. 1-Unit 2-Tan/2/Plaster	100	1487
2	03/12	PC-002	Bldg. 1-Unit 5-Blue/2/Wood	100	2662
3	03/12	PC-003	Bldg. 1-SE Corner-Pink/2/Stucco	100	BRL *
4	03/12	PC-004	Bldg. 1-Exterior Unit 1-Dark Gray/2/Wood	100	131
5	03/12	PC-005	Bldg. 2-Exterior Unit 10-Light Blue/2/Wood	100	BRL
6	03/12	PC-006	Bldg. 3-Exterior Under Balcony-White/2/Wood	100	BRL
7	03/12	PC-007	2 <sup>nd</sup> Floor-Bldg. 3-Exterior Balcony Ceiling-White/2/Wood	100	119
8	03/12	PC-008	Bldg. 4-Unit 34-Restroom-White/2/Drywall	100	BRL
9	03/12	PC-009	Bldg. 4-Unit 35-Exterior-Blue/2/Wood	100	788
10	03/12	PC-010	Bldg. 4-Unit 36-Exterior-Pink/2/Wood	100	193

<sup>a</sup> = Dilution Factor Changed

Ins. = Insufficient Sample for Analysis

\* = Excessive Substrate May Bias Sample Results

BRL = Below Reportable Limits

This report applies to the standards or procedures identified and to the samples tested only. The test results are not necessarily indicative or representative of the qualities of the lot from which the sample was taken or of apparently identical or similar products, nor do they represent an ongoing quality assurance program unless so noted.

Where it is noted that a sample with excessive substrate was submitted for laboratory analysis, such analysis may be biased. The lead content of such sample may, in actuality, be greater than reported. EMC makes no warranty, express or implied, as to the accuracy of the analysis of samples noted to have been submitted with excessive substrate. Resampling is recommended in such situations to verify original laboratory results.

These reports are for the exclusive use of the addressed client and are rendered upon the condition that they will not be reproduced wholly or in part for advertising or other purposes over our signature or in connection with our name without special written permission. Samples not destroyed in testing are retained a maximum of sixty (60) days.

ANALYST:

*Mark A. Rodocker*

Mark A. Rodocker



QA COORDINATOR:

*Kurt Kettler*

Kurt Kettler



9830 South 51<sup>st</sup> Street, Suite B-109 / PHOENIX, ARIZONA 85044 / 480-940-5294 or 800-362-3373 / FAX 480-893-1726  
emclab@emclabs.com

**LEAD (Pb) IN PAINT CHIP SAMPLES**  
EMC SOP METHOD #L01/1      EPA SW-846 METHOD 7420

EMC LAB #: L23335			DATE RECEIVED: 03/13/03		
CLIENT: Ninyo & Moore			REPORT DATE: 03/13/03		
CLIENT ADDRESS: 3155 E. Patrick Lane., Ste 12 Las Vegas, NV 89120			DATE OF ANALYSIS: 03/13/03		
PROJECT NAME: Tonopah/Pink Motel 201 Main Street			PROJECT NO.: 301218001		
EMC # L23335-	SAMPLE DATE /03	CLIENT SAMPLE #	DESCRIPTION	REPORTING LIMIT IN PPM	Pb IN PPM
11	03/12	PC-011	Bldg. 4-Unit 37-Exterior-White/2/Wood	100	BR <sub>L</sub>
12	03/12	PC-012	Bldg. 3-Stair Railing-White/2/Metal	100	BR <sub>L</sub>
13	03/12	PC-013	Pool Siding-SE Corner-Blue/2/Concrete	100	558
14	03/12	PC-014	Bldg. 5-Unit 6-Pink/2/Wood	100	994
15	03/12	PC-015	Bldg. 5-Unit 6-Blue/2/Wood	100	405
16	03/12	PC-016	Bldg. 5-Unit 4-Dark Blue/2/Wood	100	279
17	03/12	PC-017	Bldg. 4-Unit 43-Pink/2/Wood	100	195
18	03/12	PC-018	Bldg. 4-Unit 44-Blue/2/Wood	100	BR <sub>L</sub>
19	03/12	PC-019	Bldg. 4-Unit 45-White/2/Wood	100	1124

<sup>a</sup> = Dilution Factor Changed

Ins. = Insufficient Sample for Analysis

\* = Excessive Substrate May Bias Sample Results

BR<sub>L</sub> = Below Reportable Limits

This report applies to the standards or procedures identified and to the samples tested only. The test results are not necessarily indicative or representative of the qualities of the lot from which the sample was taken or of apparently identical or similar products, nor do they represent an ongoing quality assurance program unless so noted.

Where it is noted that a sample with excessive substrate was submitted for laboratory analysis, such analysis may be biased. The lead content of such sample may, in actuality, be greater than reported. EMC makes no warranty, express or implied, as to the accuracy of the analysis of samples noted to have been submitted with excessive substrate. Resampling is recommended in such situations to verify original laboratory results.

These reports are for the exclusive use of the addressed client and are rendered upon the condition that they will not be reproduced wholly or in part for advertising or other purposes over our signature or in connection with our name without special written permission. Samples not destroyed in testing are retained a maximum of sixty (60) days.

ANALYST:

*Mark A. Rodocker*

Mark A. Rodocker

QA COORDINATOR:

*Kurt Kettler*

Kurt Kettler

Page \_\_\_\_ of \_\_\_\_

**CHAIN OF CUSTODY**

EMC Laboratories

9830 S. 51<sup>ST</sup> St., Ste B-109

Phoenix, AZ 85044

(800) 362-3373 Fax (480) 893-1726

LAB#:

X23335

TAT:

Rush

Rec'd: MAR 13 AM

**COMPANY NAME:** NINYO & MOORE  
 3155 E. Patrick Lane, Ste 12  
 Las Vegas, NV 89120

**CONTACT:** Cynthia Bogdan  
**Phone/Fax:** (702) 433-0330 / (702) 433-0707  
**Email:** cbogdan@ninyoandmoore.com

**BILL TO:**

(If Different Location)

**E-MAILED**
**Now Accepting:** VISA - MASTERCARD**Price Quoted:** \$ \_\_\_\_\_ / Sample \$ \_\_\_\_\_ / Layers**COMPLETE ITEMS 1-4:** (Failure to complete any items may cause a delay in processing or analyzing your samples)**1. TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]

\*\*\*\* Prior confirmation of turnaround time is required.

\*\*\*\* Additional charges for rush analysis (please call marketing department for pricing details)

\*\*\* Laboratory analysis may be subject to delay if credit terms are not met.

**2. TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]**3. DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]

(If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

**4. Project Name:** Tonopah Pink Motel 201 Main Street**P.O. Number:** \_\_\_\_\_ **Project Number:** 301218001

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No	AIR SAMPLE INFO / COMMENTS ON	OFF	FLOW RATE
1	PC-001	3/12/03	Lead	Y N			
				Y N			
				Y N			
				Y N			
19	PC-019			Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			

**SPECIAL INSTRUCTIONS:** \_\_\_\_\_

Sample Collector: (Print) \_\_\_\_\_ (Signature) \_\_\_\_\_

Relinquished by: \_\_\_\_\_ Date/Time: \_\_\_\_\_ Received by: \_\_\_\_\_ Date/Time: 3/13/03  
 Relinquished by: Diana Feduric Date/Time: 3/13/03 Received by: Diana Feduric Date/Time: 3/13/03  
 Relinquished by: Diana Feduric Date/Time: 3/13/03 Received by: Diana Feduric Date/Time: 3/13/03

\*\* In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

**LEAD BASED PAINT BULK SAMPLE DATA SHEET**

<b>Ninno &amp; Moore</b> 3155 East Patrick Lane, Suite 12 Las Vegas, Nevada 89120 Tel: (702) 433-0330 Fax: (702) 433-0707	<b>Project Name:</b> Tonopah / Pink Motel <b>Project No.:</b> 301218001 <b>Project Manager:</b> Robert M. Troisi <b>APN:</b> <b>Site Address:</b> 201 Main Street	<b>Sampled By:</b> Robert M. Troisi <b>Sampled By:</b> Robert M. Troisi <b>Sampled By:</b> <b>Date Sampled:</b> 3/06/03 then 3/08/03	<b>Laboratory:</b> EMC <b>Tel:</b> <b>Fax:</b>
<b>CHAIN OF CUSTODY INFORMATION:</b>			
<i>Robert M. Troisi: Robert M. Troisi Diana Tedesco</i>			
LabID	Sample ID	Building Number	Sample Location
1	PC-001	#1	Bldg. #1 Unit 2 Exterior
2	PC-002	#1	Bldg. #1 Unit 5 Door
3	PC-003	#1	Bldg. #1 Se. corner walls
4	PC-004	#1	Bldg. #1 Exterior unit 1
5	PC-005	#2	Bldg. #2 Exterior unit 10
6	PC-006	#3	Bldg. #3 Exterior Balcony
7	PC-007	#3	2nd Floor Bldg. #3 exterior balcony ceiling Ceiling
8	PC-008	#4	Bldg. #4 Restroom Interior
9	PC-009	#4	Bldg. #4 Unit #35 Support post
10	PC-010	#4	Bldg. #4 Unit 36 Exterior
11	PC-011	#4	Bldg. #4 Unit #37 Exterior
12	PC-012	#3	Stair #3 Stair Railing

**LEAD BASED PAINT BULK SAMPLE DATA SHEET**

<b>Ninyo &amp; Moore</b> 3155 East Patrick Lane, Suite 12 Las Vegas, Nevada 89120 Tel: (702) 433-0330 Fax: (702) 433-0707	<b>Project Name : Tonopah / Pink Motel</b> Project No.: 301218001 Project Manager: Robert M. Troisi APN: Site Address: 201 main street	Sampled By: Robert M. Troisi Sampled By: Sampled By: Date Sampled: 03/06/03 thru 03/08/03	Laboratory: EMC
<b>Rush</b>			
<b>CHAIN OF CUSTODY INFORMATION:</b>			
<b>Relinquished By (signature)</b> <i>Robert M. Troisi</i> <i>Qianqiu Technologies</i>		<b>Company</b> Ninyo & Moore EMC	<b>Date</b> 3/2/03 3/3/03
			<b>Received By (signature)</b> <i>Qianqiu Technologies</i>
LabID	Sample ID	Building Number	Sample Location
13	PC-013	#61	pool siding S.E. corner
14	PC-014	#5	BLDG. #5 UNIT 6
15	PC-015	#5	BLDG. #5 UNIT 6
16	PC-016	#5	BLDG. #5 UNIT 4
17	PC-017	#4	BLDG #4 UNIT 43
18	PC-018	#4	BLDG. #4 UNIT 44
19	PC-019	#4	BLDG. #4 UNIT 45
			<b>Building Component</b> Pool walls exterior siding door door frame exterior siding door door frame
			<b>Sample Description</b> blue / 2/concrete pink / 2/wood blue / 2/wood dark blue / 2/wood pink / 2/wood blue / 2/wood white / 2/wood
			<b>Color</b> blue pink pink blue blue pink blue white
			<b>Estimated Surface Area</b> ✓
			<b>Condition</b> Peeling