NOTES:
1.) REPRODUCED FROM SEEGMILLER ASSOCIATES, 1979

EXPLANATION

FAULT
ALLUVIUM/BEDROCK CONTACT
TENSION CRACK

BROWN AND CALDWELL
Carson City, Nevada

DATE: DECEMBER 2002
Atlantic Richfield Company
PROJECT NUMBER 21243

FIGURE 7
PIT STRUCTURAL ELEMENTS