- Notes from 4/29/04 mtg w/ UNS, National Drycleaners + NDEP

- cc: Trust lawyers on all correspondance + Converse + Hall person.
- Paul to look @ what CCSD intends to do w/ bldg & when get back to Randy
- CAP to be commented on by directly affected parties.
- transfer of well ownership
- access transferable

Scott Ball, Randy Jackson, Chris

1/29/04
9:00am

URS has all Converse info.
↳ wants to do some more assessment to fill in data gaps they feel are there & use their exp. from other sites

- URS agrees w/ Converse's gw contours - gw traveling faster thru sands than clays w/ higher PCE conc. in clays.

John Dug Env. Dev @ CCSD **

- contact for CCSD as to plans for the vacant strip mall.

→ - wants more data from source area in regards to soil &/or gw. Also to look @ sewer line
↳ timetable: WP w/in 30 days

→ - need more characterization to East - for leading edge of plume → in street on other site of residences.
↳ timetable: WP w/in 30 days Residences?

→ need more gw characterization - ie gw parameters before presenting a RAP
↳ timetable: WP w/in 30 days

- We asked that they use concurrent paths to assess / "think about" remediation

Mtg w/ for Maryland Square Center (H-86)

April 29, 2004 - 10:00 am

Name	Company	Phone #
Chris Andres	NDEP	702-486-2858
Paul Lal	Dickerson, Dickerson	702-388-8600
Randall Jackson	NDCT	913-671-8405
Scott Ball	URS Corporation	837-1600
		direct 951-3380
Todd Croft	NDEP-LV	(702) 486-2871