

**Nevada Division of Environmental Protection
Red Tag Protocol Form**

| | |
|---|--------------------------------------|
| Facility ID No. <u>4-000742</u> | Facility Name: <u>Tahoe Biltmore</u> |
| Address: <u>SR-28 Crystal Bay, Nevada</u> | |
| Contact Present On Site? <u>Yes</u> | If yes then fill out the following: |
| Contact Name: <u>Nima Nakhjauani</u> | Contact Phone Number: _____ |

| | |
|--------------------------------------|-------------------------------|
| Date: <u>9-9-2022</u> | Time of Event: <u>10:30AM</u> |
| Inspector: <u>L. Franklin</u> | Witness: <u>B. Lucier</u> |
| Purpose of Visit? Application | |

The following table identifies the most current tank and red tag tracking information:

| Tank No. | Capacity | Product | Tank Location | Red Tag No. | Blue Seal No. 1 | Blue Seal No. 2 | Product Level |
|----------|----------|---------|---------------------|-------------|-----------------|-----------------|---------------|
| 5 | 1,000 | Diesel | Emergency Generator | N/A | N/A | N/A | Unknown |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

Method Used to Determine Product Level? Unable (If ATG attach printout to Form)

Summary of Visit: Attempted to conduct inspection to see if tank was properly put into temporary closure. Tank top and accessories are completely removed and tank is covered in dirt. Unable to determine if tank is empty and properly secured from receiving deliveries. Unable to determine if tank is capable of being monitored for leak detection.
